

Basic Condition Guide

•	Report ID:	26,049,735	Version:	1
	Created:	27 Nov 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	V		
Engine performance			
Noise	/		
Coolant condition	1		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	•		
Clutch			'
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread of	depth of	tyres)	
Left front		6	6.0 mm
Right front		6	6.4 mm
Left rear		8	3.0 mm
Right rear			6.0 mm
Spare	Yes		
Suspension			
Suspension performance		/	
Steering performance	/		
Shock absorbers		/	
Air Conditioning / Heater			
Operation	•		
Electrical / Accessories			
Head lights	/		
Tail lights	•		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	•		
Window winder FL	/		
Window winder FR	V		
Window winder RL			1
Window winder RR			V
Rear view mirrors	/		
Radio (basic test only)	1		
CD (basic test only)	V		
Number of keys	1		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			1
		1	


Make:	Volkswagen	Model:	T5
Body Style:	Van	Year:	2011
Rego No.:	GAG198	Rego Expiry:	28 Jul 2026
WoF Expiry:	20 Dec 2025	Odometer:	173,375 Kms
Good No.:	26049735	VIN:	WV1ZZZ7HZBH104215
Next Service:	167,200km's	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

rey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Water inside left side repeater indicator lens on left front guard. Large dents in right side rear sliding door

Under Carriage and Under Bonnet Inspection Comme	
Conditions During Body Inspection	Dry

Left rear shock absorber is leaking & needs replaced. Front suspension is a bit noisy when turning steering wheel.

Interior Comments		
Seats:	Average	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	

General Comments

Engine oil service is overdue. Alarm keeps going off when van is running. Windscreen washer is leaking from under left side of bonnet, leaking out of water pipe. Vinyl panel is cracking & split on base pad of driver's seat.

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	V No	Kms
Inspected by:	Jason Young			
Published by:	lished by: Glen Charlton			
Inspection Date:	27 Nov 2025			

l have	read	and	unde	rstood
this co	nditi	on a	uide	

NAME			

Reversing camera