

# **Basic Condition Guide**

•	Report ID:	26,050,166	Version:	1
	Created:	17 Dec 2025		


	ОК	Requires Attention	N/A
Engine	OK	Attention	11//
Oil level	<b>/</b>		
Smoke & fumes	<b>/</b>		
Engine performance	\( \tau \)		
Noise	<b>/</b>		
Coolant condition	/		
Cooling performance	~		
Radiator / Hoses (visual)	<b>/</b>		
Transmission			
Operation	<b>✓</b>		
Noise	/		
Clutch			~
CV joints			1
Wheel bearings	/		
Brakes			
Performance	1		
Hand brake	1		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			5 mm
Right front			7 mm
Left rear			5 mm
Right rear			5 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	<b>✓</b>		
Air Conditioning / Heater			
Operation	<b>&gt;</b>		
Electrical / Accessories			
Head lights	/		
Tail lights	<b>✓</b>		
Indicators	<b>/</b>		
Dashboard warning lights	<b>&gt;</b>		
Wipers (front & rear)	/		
Window winder FL	<b>/</b>		
Window winder FR	/		
Window winder RL			1
Window winder RR			1
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)	<b>/</b>		
Number of keys	1		
Central locking	/		
Remote locking	1		
Sat. nav. (basic test only)			V
Reversing camera	<b>/</b>		

Make:	Mitsubishi	Model:	Triton
Body Style:	Utility	Year:	2019
Rego No.:	MGH96	Rego Expiry:	29 Jan 2026
WoF Expiry:	29 Jul 2026	Odometer:	163,999 Kms
Good No.:	26050166	VIN:	MMAYLKK10KH018525
Next Service:	162,000km's	Service History:	Yes

### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

### **Body Inspection Comments**

Left side plastic moulding cover missing off front bumper. Two small stone cracks in left side of windscreen, is a double hit close together & is not repairable.

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		

Interior Comments			
Seats:	Good		
Carpets:	Good		
Panels:	Average		
Dashboard:	Average		

## **General Comments**

Centre console lid hinge is broken. Screw holes in switch blanks in dashboard & in left side of centre console.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Jason Young	
Published by:	Jason Young	
Inspection Date:	17 Dec 2025	

I hav	ve read	and	understood
thic	conditi	on a	uide.

NAME			

NATURE		