

Basic Condition Guide

•	Report ID:	26,068,475	Version:	1
	Created:	09 Nov 2025		

	OK	Requires Attention	N/A
Engine	OR	Acceleration	14// (
Oil level	V		
Smoke & fumes	1		
Engine performance	1		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			
Operation	V		
Noise	1		
Clutch			~
CV joints	1		
Wheel bearings	1		
Brakes			
Performance	V		
Hand brake	1		
Tyres (lowest observed tread	depth of	tyres)	
Left front	T T		6 mm
Right front			3 mm
Left rear			4 mm
Right rear			3 mm
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	'		
Electrical / Accessories		<u> </u>	
Head lights	V		
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	1		
Window winder FR	·		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)			1
Number of keys	1	l	
Central locking	1		
Remote locking			1
Sat. nav. (basic test only)			V
Reversing camera	1		
g carriera		<u> </u>	


Make:	Toyota	Model:	Vitz
Body Style:	Hatchback	Year:	2004
Rego No.:	GGP262	Rego Expiry:	07 Apr 2026
WoF Expiry:	26 May 2026	Odometer:	211,365 Kms
Good No.:	26068475	VIN:	7AT0H63EX11077646
Next Service:	217,000 Kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

•				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Front bumper fits poorly.

Paint condition is poor all over.

Conditions During Body Inspection

Under Carriage and Under Bonnet Inspection Comments

No coolant in coolant reservoir.

Minor engine oil leak.

Interior Comments			
Seats: Good			
Carpets:	Good		
Panels:	Average		
Dashboard:	Average, steering wheel worn.		
General Comments			

Front window washer needs adjusted.

HVAC mode selector faulty.

Engine vibration in cabin.

Drone noise in driveline.

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by: Troy Smith			
Published by: Troy Smith			
Inspection Date: 09 Nov 2025			

I have read and understood this condition guide:

NAME SIGNATURE