

# **Basic Condition Guide**

Report ID:	26,068,959	Version:	1
Created:	25 Nov 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	<b>/</b>		
Engine performance	<b>/</b>		
Noise	<b>'</b>		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	1		
Noise	1		
Clutch			V
CV joints		İ	-
Wheel bearings	1		
Brakes			
Performance	V		
Hand brake	1		
Tyres (lowest observed tread	depth of	tyres)	_
Left front	ľ		5 r
Right front			1.5 r
Left rear			6 r
Right rear			5.5 r
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	V		Π
Electrical / Accessories			
Head lights	· /		Γ
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		-
Wipers (front & rear)	V		
Window winder FL	-		
Window winder FR		•	
Window winder RL		-	
Window winder RR	.,	-	<b>_</b>
Rear view mirrors	1	-	$\vdash$
Radio (basic test only)	1	-	
CD (basic test only)	1		
Number of keys	1	ı	
Central locking	/	-	<u> </u>
Remote locking	/		
C . //		1	<i>v</i>
Sat. nav. (basic test only)  Reversing camera		<b> </b>	-

Make:	Toyota	Model:	Hiace
Body Style:	Van	Year:	2016
Rego No.:	JSK616	Rego Expiry:	26 Jan 2026
WoF Expiry:	27 Mar 2026	Odometer:	332,084 Kms
Good No.:	26068959	VIN:	JTFHT02PX00168904
Next Service:	346,000 Kms	Service History:	Yes

### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommend: full mechanical inspection prior to purchase and this can be arranged for an additional charge.

ĸey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

LR/RF door seals damaged. Tailgate badge missing.

Tailgate seal damaged. Holes drilled in inside of front doors. LH taillight broken. Stone chips in windscreen.

Highs stop light cracked. Step plates worn.

Dry Conditions During Body Inspection

## **Under Carriage and Under Bonnet Inspection Comments**

Interior Comments			
Seats: Good			
Carpets: Average, Cargo area floor torn			
Panels: Good			
Dashboard: Good			
General Comments			

LF window master switch fail.

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		<b>✓</b> Yes	No	276,088 Kms
Inspected by:	Caleb Spicer Lee			
Published by:	Caleb Spicer Lee			
Inspection Date:	25 Nov 2025			

I have read and understood
this condition guide:

NAME			