

•	Report ID: 26,082,622		Version:	3
	Created:	01 Dec 2025		


	ОК	Requires Attention	
Engine	OK	Attention	14/74
Oil level	V		
Smoke & fumes	V		
Engine performance	V		
Noise	✓		
Coolant condition	V		
Cooling performance	/		
Radiator / Hoses (visual)	•		
Transmission		ı	
Operation	/		
Noise	✓		
Clutch			/
CV joints			V
Wheel bearings	•		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		7	7.0 mm
Right front		7	7.0 mm
Left rear		(3.0 mm
Right rear			1.5 mm
Spare	Yes		
Suspension			
Suspension performance	1		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	V	Ι	
Electrical / Accessories			
Head lights	1	l	
	V		
Tail lights	V		
Indicators			
Dashboard warning lights	/		
Wipers (front & rear)	•		
Window winder FL	•		
Window winder FR	/		
Window winder RL			
Window winder RR			_
	1		
Rear view mirrors		I	
	/		
Rear view mirrors	V		
Rear view mirrors Radio (basic test only)	v 1		
Rear view mirrors Radio (basic test only) CD (basic test only)	\(\sqrt{1} \)		
Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	1 /		
Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	1		

Make:	Mitsubishi	Model:	Triton
Body Style:	Utility	Year:	2017
Rego No.:	KLA965	Rego Expiry:	09 Mar 2026
WoF Expiry:	15 Dec 2026	Odometer:	184,435 Kms
Good No.:	26082622	VIN:	MMAYYKK10HH001023
Next Service:	192,000 Kms	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Front bumper detaching on sides

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

2WD

Rust on bar behind front bumper

Interior Comments		
Seats:	Geats: drivers seat worn otherwise good	
Carpets:	Average	
Panels:	Average	
Dashboard:	Wear on steering wheel	

General Comments

Right toolbox struts worn

Reversing camera picture quality is average

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Hoani Saunders	
Published by:	Mathew Green	
Inspection Date:	26 Nov 2025	

have read and understood
this condition quide

NAME			