

Next Service:

MR0GU19G909000990

VIN:

Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends **Cooling System** a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

220000

Service History:

No

	Coolant condition	~	
	Performance	~	
Key: S = scratch	Radiator / Hoses (visual)	~	
D = dent	Transmission		
R = rust	Operation	v	
PT = paint defect	Noise	~	
C = crack	Clutch		
P = pin dent	CV joints		
"= decais	Wheel bearings	~	+
SC = stone chips W = significant scuffs	Brakes	<u> </u>	
	Performance	~	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram	Hand Brake	~	
	Tyres (lowest observed trea	d depth of tyr	res)
Headlights faded. Clear coat coming off in areas. Stone chips in front screen	Left front	6.0	n
	Right front	5.0	n
	Left rear	5.0	n
Conditions During Body Inspection: Dry	Right rear	5.0	n
	Spare	Yes	i
Under Carriage & Under Bonnet Inspection Comments	Suspension	1	

Under Carriage & Under Bonnet Inspection Comments

Runs on 91 octane fuel. Tested battery and passed

		Air Conditioning / Heater	Air Conditioning / Heater		
		Operation	~		
Interior Comments		Electrical / Accessories	Electrical / Accessories		
Seats	Average	Head lights	~		
		Tail lights	~		
Carpets	Average	Indicators	~		
Panels	Average	Dashboard warning lights	~		
		Wipers (front & rear)	~		
Dashboard	Average	Window winder FL	~		
		Window winder FR	~		
General Comm	<u>ients</u>	Window winder RL		~	
Air conditioning ar	Air conditioning and heating systems good temperature			~	
		Rear view mirrors	~		
		Radio (basic test only)	~		
		CD (basic test only)	~		
		Number of keys	2		
Road Condition	ns During Test Drive: Dry	Central locking	~		
		Remote locking	~		
Engine Timing I	Mechanism: Timing Chain	Sat. Nav. (basic test only)		~	
Evidence of Cam Belt Replacement: Not Applicable Kms:		Reversing camera		~	

Gary Adams Inspected by:

10 Apr 2025 Date:

Pass	Fail	N/A

V

V

V

V

Suspension performance

Steering performance

Shock absorbers

V

V

~

V V

mm

mm

mm

mm

Created:

Engine

Oil level

Noise

Smoke & fumes

Performance

I have read and understood this condition guide.

Name:

Signature:

24 Apr 2025

Report ID: 26,704,093 5 Version: