

Report ID: 26,787,871 5 Version: 12 May 2025 Created:

| Make: | Ford | Model: | Ranger | Body Style: | Utility | | Pass | Fail | N/A | |
|--|---|-----------------|------------------------|---------------------------------|----------------------|---|------|----------|-----|--|
| Year: | 2021 | Registration: | QLY673 | Reg Expiry: | 18 Dec 2025 | Engine | I | <u> </u> | | |
| WoF Expiry: | 18 Dec 2025 | Odometer: | 48,414 Kms | Good No: | 26787871 | Oil level | ~ | | | |
| VIN: | MPBUMFF60MX344814 | Next Service: | 56,900 kms | Service Histor | y: Yes | Smoke & fumes | ~ | | | |
| | | | | | - | Performance | ~ | | | |
| | port is not a warranty | | for ago and milaago | Parts have not | been dismonthed or | Noise | V | | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | | |
| a full mechan | ical inspection prior to | purchase and th | nis can be arranged fo | r an additional o | harge. | Coolant condition | ~ | | | |
| | | | | | | Performance | ~ | | | |
| Key: | | -0 | | -161- | | Radiator / Hoses (visual) | ~ | | | |
| S = scratch | | | | | | Transmission | | | | |
| D = dent R = rust | - HE | | | TIS | | Operation | ~ | | | |
| PT = paint defe | | | | $\left[\left(\right) \right]$ | | Noise | ~ | | | |
| C = crack | | | | | | Clutch | | | ~ | |
| P = pin dent | HIS | | | | 게 | CV joints | V | | | |
| * = decals | - Alt | | | The second | | Wheel bearings | ~ | | | |
| SC = stone chips | | | | | | Brakes | | | | |
| W = significant scuffs | | | | | | Performance | ~ | | | |
| Podylog | action Commont | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread depth of tyres | | | | |
| | | | | | | Left front 9.0 m | | | | |
| | | | | | | Right front | 9. | .0 | mm | |
| | | | | | | Left rear | 8 | .0 | mm | |
| Conditions During Body Inspection: Wet | | | | | | Right rear | 8 | .0 | mm | |
| Contactions During Dody inspection. Wet | | | | | | Spare Yes | | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | | |
| Rwd | | | | | | Suspension performance | ~ | | | |
| RWG | | | | | | Steering performance | ~ | | | |
| | | | | | | Shock absorbers | ~ | | | |
| | | | | | | Air Conditioning / Heater | | | | |
| | | | | | | Operation 🖌 | | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | | |
| Seats | Good | | | | | Head lights | ~ | | | |
| | | | | | | Tail lights | V | | | |
| Carpets | Good | | | | | Indicators | V | | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | | |
| | | | | | | Wipers (front & rear) | ~ | | | |
| Dashboa | rd Good | | | | | Window winder FL | ~ | | | |
| | | | | | | Window winder FR | ~ | | | |
| General Comments | | | | | | Window winder RL | ~ | | | |
| Body kit and accessories | | | | | | Window winder RR | ~ | | | |
| Floatnin Dellay Lid Life Life Coopling and Mendeling Coopling Floater Device Church | | | | | | Rear view mirrors | ~ | | | |
| Electric Roller Lid, Lift kit, Steelies and Muddies, Snorkel, Flares, Body Cladding. | | | | | | Radio (basic test only) | ~ | | | |
| Vehicle has | been re-registered. | | | | | CD (basic test only) | | | ~ | |
| | | | | | | Number of keys | 1 | | | |
| Road Con | Central locking | ~ | | | | | | | | |
| | | | | | | Remote locking | ~ | | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | ~ | | | |
| Evidence | of Cam Belt Replac | cement: N | lot Applicable | Kms: | | Reversing camera | ~ | | | |
| Increate | Inspected by: Marlon Espena Date: 09 May 2025 | | | | | | | | | |
| Inspected by: Marlon Espena Date: 09 May 2025 | | | | | | | | | | |
| | | | | | | | | | | |

Name: