

•	Report ID:	27,077,302	Version:	7
	Created:	05 Dec 2025		


	ОК	Requires Attention	N/A
Engine	<u> </u>	Accention	14//1
Oil level	1		
Smoke & fumes			
Engine performance	<i>J</i>		
Noise	\(\frac{1}{V} \)		
Coolant condition	<i>y</i>		
Cooling performance	<i>y</i>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	V		
Noise	<i>-</i>		
Clutch			
CV joints	V		
Wheel bearings	<i>y</i>		
Brakes			
Performance	J	1	
Hand brake	1		
	onth of	turos)	
Tyres (lowest observed tread d	epthol		1.5 mm
			5.0 mm
Right front Left rear			5.0 mm
1 1 1			
Right rear	NI/A		6.0 mm
Spare	N/A		
Suspension		I	
Suspension performance	- 1		
Steering performance			
Shock absorbers	•		
Air Conditioning / Heater		l	
Operation	/		
Electrical / Accessories		I	Г
Head lights	•		
Tail lights	-		
Indicators	V		
Dashboard warning lights			
Wipers (front & rear)	V		
Window winder FL	•		
Window winder FR	•		
Window winder RL	V		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)		'	
CD (basic test only)			_
Number of keys	1		
Central locking	•		
Remote locking	•		
Sat. nav. (basic test only)			~
Reversing camera		/	

		,	
Make:	Toyota	Model:	Aqua
Body Style:	Hatchback	Year:	2016
Rego No.:	PAA811	Rego Expiry:	24 Jan 2026
WoF Expiry:	01 Aug 2026	Odometer:	161,643 Kms
Good No.:	27077302	VIN:	7AT0H65YX22532745
Next Service:	171,000	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chins	



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Front bumper damage Stone chips in front screen. Rear bumper poor fit. Stone chips and scratches all over

Conditions During Body Inspection	Wet
Under Carriage and Under Bonnet Inspection Comm	ents

91 octane. Partial belly pans

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	

General Comments

Air conditioning and heating systems ok. Radio dosnt work so the reverse camera dosnt work.

Road Conditions During Test Drive		Wet
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Gary Adams	
Published by:	Anna Zandstra	
Inspection Date:	19 Sep 2025	

have read and understood
this condition quide

NAME			