

•	Report ID:	27,169,051	Version:	1
	Created:	14 Nov 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	1		
Smoke & fumes	1		
Engine performance	1		
Noise	•		
Coolant condition	~		
Cooling performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	/		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand brake	1		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		ţ	5.4 mm
Right front		(	6.0 mm
Left rear		4	1.4 mm
Right rear		4	4.0 mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	•		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	•		
Electrical / Accessories			
Head lights	~		
Tail lights	•		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	~		
Window winder FL	1		
Window winder FR	•		
Window winder RL	1		
Window winder RR	<b>'</b>		
Rear view mirrors	<b>'</b>		
Radio (basic test only)	<b>/</b>		
CD (basic test only)	<b>/</b>		
Number of keys	1		
Central locking	1		
Remote locking	1		
Sat. nav. (basic test only)			~
Reversing camera			

Make:	Holden	Model:	Colorado
Body Style:	Utility	Year:	2012
Rego No.:	HUJ600	Rego Expiry:	08 Nov 2025
WoF Expiry:	14 Nov 2026	Odometer:	212,476 Kms
Good No.:	27169051	VIN:	MMU148FH0DH611122
Next Service:	218000 Kms	Service History:	No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

rey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram  $\,$ 

# **Body Inspection Comments**

Roof aerial broken.

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		

Right front outer CV boot clip leaking.

Interior Comments		
Seats:	Poor	
Carpets:	Average	
Panels:	Average	
Dashboard: Average		

## **General Comments**

Left windows tint bubbling. Drivers seat base side bolster worn. Steering wheel worn. Hole in rear seat base right side. Left mirror not adjusting. Check turn signal warning on dash.

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by:	Chris McQuade		
Published by:	Nitiphum Yordsiri		
Inspection Date:	05 Nov 2025		

l have	read	and	unde	rstood
this co	nditi	on a	uide	

NAME		