

# **Basic Condition Guide**

•	Report ID:	27,178,299	Version:	1
	Created:	23 Dec 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	<b>/</b>		
Smoke & fumes	<b>/</b>		
Engine performance	✓ ✓		
Noise	/		
Coolant condition	<b>/</b>		
Cooling performance	<b>✓</b>		
Radiator / Hoses (visual)	<b>/</b>		
Transmission		<u> </u>	
Operation	<b>V</b>		
Noise	~		
Clutch			1
CV joints	<b>/</b>		
Wheel bearings	<b>/</b>		
Brakes			
Performance	/		
Hand brake	<b>/</b>		
Tyres (lowest observed tread d	epth of	tvres)	
Left front	1 01		6.0 mm
Right front			6.0 mm
Left rear			6.0 mm
Right rear			6.0 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	<b>/</b>		
Shock absorbers	<b>/</b>		
Air Conditioning / Heater			
Operation	<b>/</b>		
Electrical / Accessories			
Head lights		·	
Tail lights		<b>/</b>	
Indicators	<b>/</b>		
Dashboard warning lights	·		
Wipers (front & rear)			
Window winder FL	·		
Window winder FR	~		
Window winder RL			
Window winder RR	<b>V</b>		
Rear view mirrors			
Radio (basic test only)	<b>V</b>		
CD (basic test only)	~		
Number of keys	2	l .	
Central locking			
Remote locking			
Sat. nav. (basic test only)			
Reversing camera			
neversing carriera			


Make:	Subaru	Model:	Forester
Body Style:	SUV	Year:	2010
Rego No.:	FHR408	Rego Expiry:	17 Dec 2025
WoF Expiry:	14 May 2026	Odometer:	208,305 Kms
Good No.:	27178299	VIN:	JF2SH9KL5AG040981
Next Service:	218,200kms	Service History:	No

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

# Key

W = Significant scuffs S = ScratchR = RustC = Crack\* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### **Body Inspection Comments**

Left tail light is cracked.(Water in it). One of cargo anchor cover is missing.

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comm	ents

Leaking from engine.

Interior Comments			
Seats:	Good		
Carpets:	Small hole in right front.		
Panels:	Good		
Dashboard: Good			
General Comments			

## Left low beam is not operating. Rear wiper needs a new blade.

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	<b>V</b> No	Kms
Inspected by:	Yuki Itohara			
Published by:	Tiaan Pienaar			
Inspection Date:	19 Dec 2025			

l have	read	and	unde	rstood
this co	nditi	on a	uide	

NAME			