

# **Basic Condition Guide**

•	Report ID:	27,785,431	Version:	1
	Created:	14 Nov 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	<b>/</b>		
Engine performance	V V		
Noise	/		
Coolant condition		~	
Cooling performance	/		
Radiator / Hoses (visual)	<b>/</b>		
Transmission			
Operation	<b>/</b>		
Noise	<b>/</b>		
Clutch			~
CV joints	<b>/</b>		
Wheel bearings	<b>/</b>		
Brakes			
Performance	<b>/</b>		
Hand brake	<b>/</b>		
Tyres (lowest observed tread de	epth of	tyres)	
Left front			8 mm
Right front			8 mm
Left rear			7 mm
Right rear			7 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	<b>/</b>		
Shock absorbers	<b>/</b>		
Air Conditioning / Heater		<u> </u>	
Operation	<b>/</b>		
Electrical / Accessories			
Head lights	/		
Tail lights	~		
Indicators	<b>✓</b>		
Dashboard warning lights			
Wipers (front & rear)	V V		
Window winder FL	<b>/</b>		
Window winder FR	·		
Window winder RL			
Window winder RR			
Rear view mirrors	~		
Radio (basic test only)			
CD (basic test only)			
Number of keys	1	I.	
Central locking	<b>V</b>		1
Remote locking	*	· ·	<del>                                     </del>
Sat. nav. (basic test only)			-
Reversing camera			1
g sumeru		<u> </u>	


Make:	Toyota	Model:	Hiace
Body Style:	Van	Year:	2008
Rego No.:	LHY207	Rego Expiry:	17 Jun 2025
WoF Expiry:	10 May 2025	Odometer:	208,259 Kms
Good No.:	27785431	VIN:	7AT0H60FX18081523
Next Service:	205,711kms	Service History:	No

### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Key

S = Scratch R = Rust C = Crack \*= Decals W = Significant scuffs D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Service overdue

Conditions During Body Inspection	Wet		
Under Carriage and Under Bonnet Inspection Comments			

# Interior Comments Seats: Poor Carpets: Poor Panels: Poor Dashboard: Average

### **General Comments**

Driver seat torn, steering wheel worn wheel torn, radio unsecured,tail gate view mirror broken, passenger seat belt frayed, both fog light bulb missing, drive belt cracked, steering rock leak, underbody rust, r front wheel play,

Road Conditions During Test Drive		Wet
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Marlon Espena	
Published by:	Marlon Espena	
Inspection Date:	14 Nov 2025	

П	nave	read	and	unde	rstood
tł	nis co	nditi	on a	uide	

NAME			