

•	Report ID:	27,791,175	Version:	2
	Created:	19 Nov 2025		

Requires Attention

N/A

7.0 mm 7.0 mm 7.0 mm 7.0 mm

Ea Ti	nue	S Bas	sic Condition Guide	Created:	19 Nov 2025	ve	ersion:
				Cicutcu.	101407 2020		
Make:	Holden	Model:	Colorado			ОК	Requ Atte
Body Style:	Utility	Year:	2015	Engine	OK	Atte	
Rego No.:	JDU511	Rego Expiry:	22 Jun 2026	Oil level		V	
WoF Expiry:	27 Jun 2026	Odometer:	112,602 Kms	Smoke & fumes		1	$\vdash$
Good No.:	27791175	VIN:	MMU148FK0GH601168	Engine performance		V	$\vdash$
Next Service:	No Sticker	Service History:	Yes	Noise		1	
lote: This report is not a warranty				Coolant condition		1	
his report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or liagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a ull mechanical inspection prior to purchase and this can be arranged for an additional charge.					Cooling performance		t
	pection prior to purchase an	d this can be arranged	of for an additional charge.		Hoses (visual)	1	t
<b>Key</b> S = Scratch F	R = Rust	Crack *= Dec	cals W = Significant scuffs	Transmiss			1
	PT = Paint defect P = P		one Chips	Operation		V	Τ
				Noise		1	t
P W		D W P W	W	Clutch			1
				CV joints		1	1
		+		Wheel bearings		1	t
sc w				Brakes			
				Performance		V	Τ
			PT R SC	Hand brake		1	$\vdash$
sc w	HA			Tyres (lowest observed tread depth of tyres)			tyres)
	THE OF			Left front		Ī	
			PW	Right front			
				Left rear			
PW		D W D W	PW	Right rear			
Note: some defects	s and blemishes may not be	displayed in the diag	ıram	Spare		Yes	
	ion Comments			Suspensio	n		
Paint defect or	n canopy roof			Suspension	n performance	V	
Holes on roof -	Have been plugged			Steering pe	erformance	1	
				Shock abso	orbers	1	
Conditions Du	iring Body Inspection		Dry	Air Conditioning / Heater			
Under Carria	ge and Under Bonnet	Inspection Com	ments	Operation 🗸			
CV joint seal le	-			Electrical /	Accessories		
Gearbox select Underbody rus	tor seal leaking (requir	es further investig	gation)	Head light:	5	<b>/</b>	
Onderbody rus	·			Tail lights		1	
Interior Com	ments			Indicators		1	
Seats:	Good			Dashboard	warning lights	1	
Carpets:	Good			Wipers (fro	nt & rear)	1	
Panels: Good			Window w		~		
Dashboard: dashboard customised				Window w	inder FR	1	
General Comments				Window w	inder RL	1	
Dashboard has holes				Window w	inder RR	~	
One key remote not operating / Equipped with canopy keys				Rear view r	mirrors	1	
Partial service history Noises from front suspension					c test only)	1	†
	ons During Test Drive	Dry		CD (basic t			<u> </u>
Engine Timing Mechanism Cambelt				Number of		2	
					,-		_

I have read and understood this condition guide:

Inspection Date: 14 Nov 2025

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Kilipati Mae

**Bruce Screaton** 

NAME			

No

112,511 Kms

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

✓ Yes

SIGNATURE			

1

1