

# **Basic Condition Guide**

•	Report ID: 27,792,415		Version:	1
	Created:	11 Dec 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	1		
Smoke & fumes	1		
Engine performance	\( \times \)		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission	<u> </u>		
Operation	1		
Noise	1		
Clutch			
CV joints	1		
Wheel bearings	1		
Brakes			
Performance	<b>/</b>		
Hand brake	<i>'</i>	-	
Tyres (lowest observed tread d	enth of	tyres)	
Left front	eptiroi		3.8 mm
Right front			1.5 mm
Left rear			1.9 mm
Right rear	Yes		1.5 mm
Spare	res		
Suspension		<u> </u>	
Suspension performance	•		
Steering performance			
Shock absorbers			
Air Conditioning / Heater			
Operation			
Electrical / Accessories			
Head lights	•		
Tail lights	/		
Indicators	<b>/</b>		
Dashboard warning lights	•		
Wipers (front & rear)	/		
Window winder FL			
Window winder FR	/		
Window winder RL	/		
Window winder RR	\( \sqrt{ \sq}} \sqrt{ \qq \sqrt{ \sq}} \sqrt{ \sqrt{ \sqrt{ \sqrt{ \sqrt{ \sq}} \squintit{ \sq} \q \sq \sint{ \sq}} \sqrt{ \sqrt{ \sq}}  \sq \sintiin \s		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			
Number of keys	2		
Central locking	/		
Central locking  Remote locking	<i>'</i>		
	<i>y</i>		•


Make:	Suzuki	Model:	Vitara
Body Style:	SUV	Year:	2017
Rego No.:	KKE296	Rego Expiry:	19 Feb 2026
WoF Expiry:	29 Sep 2026	Odometer:	172,500 Kms
Good No.:	27792415	VIN:	TSMLYE21S00302612
Next Service:	176300 Kms	Service History:	No

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

# Key

S = Scratch R = Rust C = Crack \*= Decals W = Significant scuffs D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram  $\,$ 

#### **Body Inspection Comments**

Conditions During Body Inspection	Wet		
Under Carriage and Under Bonnet Inspection Comments			

# Interior Comments Seats: Average Carpets: Average Panels: Average Dashboard: Average General Comments

### Left front door window working from master switch but not from door.

Road Condition	s During Test Drive	Wet	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by:	Chris McQuade		
Published by:	Jason Bucksey		
Inspection Date:	26 Nov 2025		

have read and	understood
his condition of	nuido.

NAME			