

# **Basic Condition Guide**

•	Report ID:	port ID: 27,801,414		4
	Created:	04 Dec 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	~		
Smoke & fumes	/		
Engine performance	~		
Noise	<i>V V</i>		
Coolant condition			
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	<b>✓</b>		
Noise	<b>V</b>		
Clutch	<b>✓</b>		
CV joints			<b>/</b>
Wheel bearings	<b>✓</b>		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		4	1.0 mm
Right front		Ę	5.0 mm
Left rear		3	3.0 mm
Right rear		3	3.0 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	<b>/</b>		
Shock absorbers	<b>/</b>		
Air Conditioning / Heater			
Operation	<b>✓</b>		
Electrical / Accessories			
Head lights	<b>✓</b>		
Tail lights	<b>✓</b>		
Indicators	\( \sigma \)		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	<b>✓</b>		
Window winder RR	<b>✓</b>		
Rear view mirrors		•	
Radio (basic test only)	/		
CD (basic test only)	/		
Number of keys	2		
Central locking	<b>/</b>		
Remote locking	<b>/</b>		
Sat. nav. (basic test only)			<b>/</b>
Reversing camera	/		


Make:	Foton	Model:	Tunland
Body Style:	Utility	Year:	2014
Rego No.:	HSW910	Rego Expiry:	02 Dec 2025
WoF Expiry:	09 Oct 2026	Odometer:	124,180 Kms
Good No.:	27801414	VIN:	LVAV2MBB5EJ037334
Next Service:	134,180km	Service History:	No

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

#### Kev

icy				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Paintwork's poor and faded with clear coat coming off in spots. Front bumper damaged. Lhs running board hanging down. Rear bumper poor fit.

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	

### **General Comments**

Air conditioning and heating systems along with reverse camera ok. Centre rhs air vent doesn't direct air flow. Lf main beam nw. Fog lights nw. Mirrors don't self adjust

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Gary Adams	
Published by:	Anna Zandstra	
Inspection Date:	21 Nov 2025	

I have read and understood
this condition guide:

NAME			

SI	GN	AT	URF	