

•	Report ID:	27,801,467	Version:	2
	Created:	27 Nov 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise	V		
Coolant condition	V		
Cooling performance	V		
Radiator / Hoses (visual)	V		
Transmission			
Operation	V		
Noise	1		
Clutch			1
CV joints	1		
Wheel bearings	1		
Brakes	-		
Performance	V		
Hand brake	1		
Tyres (lowest observed tread	depth of	tyres)	
Left front			3.5 mn
Right front		3	3.5 mn
Left rear			1.0 mn
Right rear			5.0 mn
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation Operation	V		
Electrical / Accessories			
Head lights	· ·		
Tail lights	1		
Indicators	1		
	1		
Dashboard warning lights			
Wipers (front & rear) Window winder FL	<i>\</i>		
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	-	
Window winder FR	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	1	
Window winder RL	-		
Window winder RR	-	"	
Rear view mirrors	-		
Radio (basic test only)	V		
CD (basic test only)			
Number of keys	1		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)		ļ	/
Reversing camera		/	1

Make:	Subaru	Model:	Legacy
Body Style:	Wagon	Year:	2006
Rego No.:	LAE13	Rego Expiry:	10 Aug 2026
WoF Expiry:	17 Oct 2026	Odometer:	165,670 Kms
Good No.:	27801467	VIN:	7AT0GF0BX17041962
Next Service:	166,474 Kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key * = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Paint defect on front grill. Paint defect on rear spoiler.

Conditions During Body Inspection	Wet			
Under Carriage and Under Bonnet Inspection Comments				

Minor engine oil leak.

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels: Average		
Dashboard: Average, Dashboard vinyl cracked		
C		

General Comments

Cambelt due at 200,000 Kms. RR window master switch fail. Reverse camera not working.

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		✓ Yes	No	200,000 Kms
Inspected by:	Caleb Spicer Lee			
Published by:	Shanna Bullion			
Inspection Date:	24 Nov 2025			

I have read and understood
this condition guide:

NAME		