

•	Report ID:	27,802,086	Version:	1
	Created:	25 Nov 2025		

	11000	Raci	c Condition Guide	Report ID:	27,802,086	Vei	rsion: 1	
	nue	<u> </u>		Created:	25 Nov 2025			
Make:	Subaru	Model:	Legacy				Requires	
Body Style:	Wagon	Year:	2007	Fig. et a.		OK	Attention	N/A
Rego No.:	KTF771	Rego Expiry:	31 Jul 2026	Engine				
NoF Expiry:	09 Jul 2026	Odometer:	266,275 Kms	Oil level		/		-
Good No.:	27802086	VIN:	7AT0GF0BX17047371	Smoke & fu		/		-
Next Service:	268,000 Kms	Service History:	No	Engine per	formance	V		
te: This report is		,		Noise		/		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or					ndition	V		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a ull mechanical inspection prior to purchase and this can be arranged for an additional charge.			Cooling pe		/			
≘y					Hoses (visual)	/		
= Scratch R	= Rust $C=C$	Crack *= Deca	ls W = Significant scuffs	Transmiss	ion			
= Dent P	T = Paint defect P = P	in dent SC = Sto	ne Chips	Operation		/		<u> </u>
S SC		s sc	SW	Noise		V		<u> </u>
$\overline{}$	$\overline{}$	\top		Clutch				~
	\ \ <u>\</u>		SDW	CV joints		/		
				Wheel bea	rings	/		
$-\!$				Brakes				
	M 1		PT	Performan	ce	/		
				Hand brake	2	/		
S P SC				Tyres (lowest observed tread depth of tyres)				
S			Left front		4.9 m			
			Right front		4.6 r		4.6 m	
			Left rear		5.7		5.7 m	
SW		<u>s</u> s	SW	Right rear		3.8		3.8 m
Note: some defects and blemishes may not be displayed in the diagram			Spare		Yes			
Body Inspecti	ion Comments			Suspensio	n			
	k light is not working			Suspension	n performance	1		
Side mirror housing has paint defects Front windscreen washer jets not workingg			Steering pe	erformance	V			
TOTIL WITHGSCIE	en washer jets not wo	rkingg		Shock abso	orbers	1		
Zonditions Du	ring Body Inspection		Dry	Air Conditioning / Heater				
Under Carriage and Under Bonnet Inspection Comments				Operation		1		
Oil leak				Electrical /	Accessories			
			Head lights	5		V		
				Tail lights		1		
nterior Comr	nents			Indicators		1		
Seats:	Good				warning lights	1		
Carpets:	Good			Wipers (fro		1		
Panels: Average		Window w		1				
Dashboard: Good			Window w		1			
General Comments			Window w		1			
A/C screen to dim/not visible			Window w		1			
CD drive feels like there's a CD stuck			VVIII IGOVV VV	inder nit	+		—	

interior Confinents				
Seats:	Good			
Carpets:	Good			
Panels:	Average			
Dashboard:	Good			
Conoral Comments				

CD drive feels like there's a CD stuck

On board screen is in Japanese, unsure if it functions correctly

Road Condition	s During Test Drive	Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		✓ Yes	No	216,500 Kms
Inspected by:	Logan Lane			
Published by:	Janine Bell			
Inspection Date:	22 Nov 2025			

I have read and understood
this condition guide:

NAME			

SIGNATURE		

1

2

1

•

•

Rear view mirrors

Radio (basic test only)

Sat. nav. (basic test only) Reversing camera

CD (basic test only)

Number of keys

Central locking Remote locking