

Basic Condition Guide

•	Report ID:	Report ID: 27,804,529		1
	Created:	24 Nov 2025		

		Requires	
Engine	OK	Attention	N/A
Oil level			
Smoke & fumes			- V
Engine performance	1		-
Noise	+		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			
Operation	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	<u> </u>	
Noise	1		
Clutch	+		
CV joints			<u> </u>
Wheel bearings	1		
Brakes			
Performance	J	1	
Hand brake	1		
	denth of	tures)	
Tyres (lowest observed tread Left front	черитот	tyles)	5 mm
Right front			
Left rear			
Right rear	N/A		3 mm
Spare Suspension	IN/A		
Suspension performance	1	l	Γ
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	1	l	Π
Electrical / Accessories			
Head lights	1	1	1
Tail lights	· ·		
Indicators	V		
Dashboard warning lights	· ·		
Wipers (front & rear)	1		
Window winder FL	1		
Window winder FR	1		
Window winder RL			
Window winder RR			
Rear view mirrors	1		<u> </u>
Radio (basic test only)	1		
CD (basic test only)			
Number of keys	3	l	
Central locking	1	1	Ι
Remote locking	· ·		
Sat. nav. (basic test only)	1		
Reversing camera	1		
neversing carriera		<u> </u>	<u> </u>


			T
Make:	Ford	Model:	Transit
Body Style:	Van	Year:	2023
Rego No.:	QCZ622	Rego Expiry:	23 Nov 2025
WoF Expiry:	20 Jul 2026	Odometer:	44,077 Kms
Good No.:	27804529	VIN:	WF0EXXTTRBNG18439
Next Service:	unknown	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack *= Decals W = Significant scuffs D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Left wing mirror indicator lens broken. Spare wheel missing.
Left tail light cracked. 2 wheel trims missing.

Left rear corner panel dented. Right wing mirror lower glass missing.

Conditions During Body Inspection Dry Under Carriage and Under Bonnet Inspection Comments

Transmission / motor oil leak.

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Scratches, dents, panel & rear door frame damage.	
Dashboard:	Drivers sun visor needs refitting.	

General Comments

Charging cable missing. Full electric Transit van.

Road Conditions During Test Drive		Wet		
Engine Timing Mechanism		Unknown		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Daryll Timms			
Published by:	Daryll Timms			
Inspection Date:	24 Nov 2025			

I have read and understood
this condition guide:

NAME			