


Basic Condition Guide

| • | Report ID: 27,810,708 | | Version: | 1 | |
|---|-----------------------|-------------|----------|---|--|
| | Created: | 27 Nov 2025 | | | |

| Make: | Honda | Model: | FIT Shuttle |
|-----------------------|-----------------------------|-------------------------|--|
| Body Style: | Wagon | Year: | 2013 |
| Rego No.: | QNM252 | Rego Expiry: | 22 Apr 2026 |
| WoF Expiry: | 12 Mar 2026 | Odometer: | 115,364 Kms |
| Good No.: | 27810708 | VIN: | 7AT08G2YX24108909 |
| Next Service: | 124,000 kms | Service History: | No |
| diagnostic testing un | only. Consideration is made | een driven up to 50km/l | arts have not been dismantled or h from cold. The Vendor recommends a or an additional charge. |

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

| Conditions During Body Inspection | Dry | | |
|---|-----|--|--|
| Under Carriage and Under Bonnet Inspection Comments | | | |

| Interior Comm | ents |
|---------------|---------|
| Seats: | Good |
| Carpets: | Average |
| Panels: | Average |
| Dashboard: | Good |

General Comments

Spanner dash light on HMMF, windscreen rubber torn, both rear tyres cracked, r front tyre side wall low,

| Road Conditions During Test Drive | | Dry |
|-----------------------------------|---------------|--------------|
| Engine Timing Mechanism | | Timing Chain |
| Evidence of Cam Belt Replacement | | Yes No Kms |
| Inspected by: | Marlon Espena | |
| Published by: | Marlon Espena | |
| Inspection Date: | 27 Nov 2025 | |

| I have read and understood |
|----------------------------|
| this condition quido: |

| NAME | | | |
|------|--|--|--|

| | ОК | Requires Attention | N/A |
|--------------------------------|------------|-----------------------|----------|
| Engine | | | |
| Oil level | / | | |
| Smoke & fumes | / | | |
| Engine performance | 1 | | |
| Noise | 1 | | |
| Coolant condition | \(\tau \) | | |
| Cooling performance | ~ | | |
| Radiator / Hoses (visual) | / | | |
| Transmission | | | |
| Operation | / | | |
| Noise | / | | |
| Clutch | | | • |
| CV joints | / | | |
| Wheel bearings | / | | |
| Brakes | | | |
| Performance | V | | |
| Hand brake | / | | |
| Tyres (lowest observed tread d | epth of | tyres) | |
| Left front | | 3 | 3.5 mm |
| Right front | | | 4 mm |
| Left rear | | | 3 mm |
| Right rear | | | 2 mm |
| Spare | N/A | | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ' | | |
| Electrical / Accessories | 1 | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | V V | | |
| Wipers (front & rear) | • | | |
| Window winder FL | • | | |
| Window winder FR | V | | |
| Window winder RL | | | |
| Window winder RR | • | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | • | | |
| CD (basic test only) | / | | |
| Number of keys | 1 | . | |
| Central locking | / | | |
| Remote locking | / | | |
| Sat. nav. (basic test only) | | | / |
| Reversing camera | | | |