

•	Report ID: 27,811,778		Version:	2
	Created:	08 Dec 2025		

	1000	Raci	c Condition Guide	Report ID:	27,811,778	Ve	rsion: 2	
	nuer	<u> </u>	C Condition Guide	Created:	08 Dec 2025			
Make:	Hyundai	Model:	Tucson				Requires	
Body Style:	SUV	Year:	2007	_		OK	Attention	N/A
Rego No.:	PDM239	Rego Expiry:	01 Nov 2025	Engine				
WoF Expiry:	03 Feb 2026	Odometer:	108,097 Kms	Oil level		/		
Good No.:	27811778	VIN:	KMHJN81BR7U572475	Smoke & fu	mes	/		
Next Service:	118100 Kms	Service History:	No	Engine per	formance	/		
		Service History.	140	Noise		/		
Note: This report is a guide	only. Consideration is made	e for age and mileage. Pa	arts have not been dismantled or	Coolant coi	ndition	1		
diagnostic testing un- full mechanical inspe	dertaken. The vehicle has bection prior to purchase and	een driven up to 50km/h d this can be arranged f	n from cold. The Vendor recommends a or an additional charge.	Cooling pe	rformance	/		
Key				Radiator / H	loses (visual)	/		
-	= Rust C = C	rack *= Deca	ls W = Significant scuffs	Transmissi	on			
D = Dent PT	= Paint defect $P = Pi$	in dent SC = Stor	ne Chips	Operation		/		
		S P SC		Noise		~		
		30		Clutch				1
			SD	CV joints		1		
				Wheel bear	ings	1		
$\bigcup \mathcal{A}$				Brakes				
	9 11			Performand	 ce	V		
		—	sc	Hand brake	<u> </u>	1		
SC	R			Tyres (lowest observed tread depth of tyres)				
\mathcal{C}				Left front		6.3 mm		
			(Q)	Right front			5	5.4 mm
				Left rear			6	 3.1 mm
S (P	SSS	Right rear		6.5 mm		
Note: some defects and blemishes may not be displayed in the diagram				Spare		Yes		
Body Inspection		ansprayed in the diagra		Suspensio	n			
Chips in Windso	creen CVA.			Suspension	performance	V		
				Steering pe	erformance	1		
				Shock abso	rbers	1		
Conditions During Body Inspection Dry					Air Conditioning / Heater			
Under Carriage and Under Bonnet Inspection Comments				Operation			·	
				Electrical /	Accessories			
				Head lights	i	'		
				Tail lights		1		
Interior Comments						1		
Seats: Average				Dashboard	warning lights	1		
Carpets:	Average			Wipers (fro		1		
Panels:	Average			Window wi		1		
Dashboard:	Average			Window wi		1		
Sastisoura.	Average					<u> </u>	-	

Interior Comm	Interior Comments				
Seats:	Average				
Carpets:	Average				
Panels:	Average				
Dashboard: Average					
General Comments					

Air Con not working.

Road Condition	s During Test Drive	Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		✓ Yes	No	99,234 Kms
Inspected by:	Chris McQuade			
Published by:	Chris McQuade			
Inspection Date:	02 Dec 2025			

I have read and understood
this condition guide:

NAME			

SIGNATURE		

1

1 2

1

•

Window winder RL

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Sat. nav. (basic test only) Reversing camera

Number of keys

Central locking Remote locking