

•	Report ID:	27,819,275	Version:	1
	Created:	02 Dec 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	V V V		
Noise	<b>/</b>		
Coolant condition	<b>/</b>		
Cooling performance	<b>/</b>		
Radiator / Hoses (visual)	<b>/</b>		
Transmission		<u> </u>	
Operation	<b>/</b>		
Noise	<b>/</b>		
Clutch			<b>/</b>
CV joints	<b>/</b>		
Wheel bearings	<b>/</b>		
Brakes			
Performance			
Hand brake	<b>/</b>		
Tyres (lowest observed tread de	epth of	tyres)	
Left front	•		4 mm
Right front			4 mm
Left rear			5.5 mm
Right rear			1.5 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	<b>/</b>		
Indicators	/		
Dashboard warning lights	<b>/</b>		
Wipers (front & rear)	<b>✓</b>		
Window winder FL	<b>/</b>		
Window winder FR	<b>/</b>		
Window winder RL			
Window winder RR	<b>V</b>		
Rear view mirrors	<b>✓</b>		
Radio (basic test only)			
CD (basic test only)			<b>/</b>
Number of keys	2	I.	
Central locking			
Remote locking	· /		
Sat. nav. (basic test only)	-		<b>/</b>
Reversing camera	<b>/</b>		-
J	•		

Make:	Toyota	Model:	Aqua	
Body Style:	Hatchback	Year:	2018	
Rego No.:	QUF618	Rego Expiry:	10 Mar 2026	
WoF Expiry:	13 Mar 2026	Odometer:	127,172 Kms	
Good No.:	27819275	VIN:	7AT0H65YX24752698	
Next Service:	no sticker	Service History:	No	
Note: This are out in a to a suppose to				

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Kev

,				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D - Dent	DT - Paint defect	D - Din dont	SC - Stone Chins	



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Passenger seat belt frayed, both rear tyre side wall cracked,L minor indicator lens cracked,

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Interior Comments		
Seats:	Good	
Carpets:	Average	
Panels:	Average	
Dashboard:	Good	
- 1-		

# **General Comments**

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Marlon Espena	
Published by:	Marlon Espena	
Inspection Date:	02 Dec 2025	

I have read and understood this condition guide:

NAME			