

•	Report ID:	27,820,288	Version:	1
	Created:	10 Dec 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	~		
Smoke & fumes	V		
Engine performance	V		
Noise	~		
Coolant condition	/		
Cooling performance	~		
Radiator / Hoses (visual)	V		
Transmission			
Operation	/		
Noise	/		
Clutch			~
CV joints	V		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		5	5.0 mm
Right front		5	5.0 mm
Left rear		6	3.0 mm
Right rear		6	3.0 mm
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	'		
Shock absorbers	~		
Air Conditioning / Heater			
Operation		/	
Electrical / Accessories		1	
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	•		
Radio (basic test only)	/		
CD (basic test only)	/		<u> </u>
Number of keys	2		
Central locking	/		
Remote locking	•		
Sat. nav. (basic test only)			~
Reversing camera			/

Make:	Ford	Model:	Focus
Body Style:	Hatchback	Year:	2014
Rego No.:	HTS314	Rego Expiry:	25 Sep 2026
WoF Expiry:	04 Feb 2026	Odometer:	123,402 Kms
Good No.:	27820288	VIN:	MPB1XXMXB1EB85218
Next Service:	132,300kms	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

W = Significant scuffs S = ScratchR = RustC = Crack* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Left door mirror bezel is broken. Part of rear wiper arm is broken. (Operating). Small stone crack at right side edge of windshield.

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Interior Comm	ents
Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

General Comments

AC is not cold.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Yuki Itohara	
Published by:	Tiaan Pienaar	
Inspection Date:	01 Dec 2025	

I have	read	and	unders	tooc
this co	nditi	on a	uide	

NAME			