

Basic Condition Guide

| Report ID: | 27,822,189 | Version: | 1 | |
|------------|-------------|----------|---|--|
| Created: | 12 Dec 2025 | | | |

N/A

5 mm 5 mm 6 mm 6 mm

| | | | | Created: | 12 Dec 2025 | | |
|------------------------|--|---------------------------|---------------------|--|---------------------------------------|----------|--|
| Make: | Holden | Model: | Cruze | | | | Requires |
| Body Style: | Wagon | Year: | 2014 | Fusing | | OK | Attention |
| Rego No.: | HQR871 | Rego Expiry: | 22 Mar 2026 | Engine | | | |
| WoF Expiry: | 16 Oct 2026 | Odometer: | 43,048 Kms | Oil level | | / | |
| Good No.: 27822189 | | VIN: | KL3JA35MJEK601654 | Smoke & fumes | | / | - |
| Next Service: | 52,000 kms | Service History: | No | Engine performance | | / | - |
| Note: This report is | | , | Noise | | / | - | |
| This report is a guide | e only. Consideration is mad ndertaken. The vehicle has b | Coolant condition | | / | | | |
| | ection prior to purchase an | | Cooling performance | | / | <u> </u> | |
| Key | | Radiator / Hoses (visual) | | | | | |
| | = Rust $C = C$ | | | Transmiss | | | l l |
| D = Dent P | T = Paint defect P = P | in dent SC = Sto | one Chips | Operation | | / | |
| | | | | Noise | | / | |
| | | \top | | Clutch | | | |
| | | | SD | CV joints | | / | <u> </u> |
| S D | | | | Wheel bea | arings | / | |
| W A | | | | Brakes | | | |
| | M 11 | | | Performan | ice | / | |
| 11 | | | | Hand brak | ie | / | |
| | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | Left front | | | |
| | | | | Right front | t | | |
| | \angle | | | Left rear | | | |
| | |][| | Right rear | | | |
| Note: some defects | and blemishes may not be | e displayed in the diagr | am | Spare Yes | | | |
| Body Inspecti | ion Comments | | | Suspensio | on | | |
| Engine oil leak, | , underbody subframe | rust, | | Suspensio | n performance | / | |
| | | | | Steering p | erformance | V | |
| | | | | Shock abso | orbers | V | |
| Conditions Du | ring Body Inspection | | Dry | Air Conditioning / Heater | | | |
| Under Carriag | ge and Under Bonnet | Inspection Comr | nents | | | / | |
| | | | | Electrical | / Accessories | | • |
| | | | | Head light | is . | / | |
| | | | | Tail lights | | 1 | |
| Interior Comm | nents | | | Indicators | | V | |
| Seats: | Good | | | Dashboard | d warning lights | 1 | |
| Carpets: | Good | | | Wipers (fro | | 1 | |
| Panels: Good | | | | Window w | | 1 | <u> </u> |
| Dashboard: Good | | | | Window w | | 1 | |
| General Com | | | Window w | | 1 | | |
| Washer jet not | | | | Window w | | 1 | |
| , | <u>.</u> | | | Rear view | | 1 | † |
| | | | | | sic test only) | 1 | + |
| Road Condition | ns During Test Drive | Dry | | CD (basic t | · · · · · · · · · · · · · · · · · · · | V | + |
| | | Timing Chain | Number of | • | 1 | <u></u> | |
| | | | | | | · · | T |
| | - | Yes | No Kms | Central loc | | - | - |
| Inspected by: | Marlon Espena | | | Remote lo | cking | / | 1 |

I have read and understood this condition guide:

Inspection Date: 12 Dec 2025

Marlon Espena

Published by:

NAME

SIGNATURE

Sat. nav. (basic test only)

Reversing camera