

Basic Condition Guide

Report ID:	27,826,996	Version:	3	
Created:	09 Dec 2025			


	ОК	Requires Attention	N/A
Engine			
Oil level	~		
Smoke & fumes	/		
Engine performance	/		
Noise	~		
Coolant condition		~	
Cooling performance	~		
Radiator / Hoses (visual)	/		
Transmission			
Operation	~		
Noise	✓		
Clutch			'
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		2	2.0 mm
Right front		2	2.5 mm
Left rear			1.0 mm
Right rear			1.5 mm
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater		ı	
Operation	✓		
Electrical / Accessories			
Head lights	<i>'</i>		
Tail lights			
Indicators	✓		
Dashboard warning lights	/		
Wipers (front & rear)	<u> </u>		
Window winder FL	<u> </u>		
Window winder FR			
Window winder RL	/		
Window winder RR			
Rear view mirrors			
Radio (basic test only)	•		
CD (basic test only)			
Number of keys	1	Г	
Central locking	•		
Remote locking			
Sat. nav. (basic test only)			
Reversing camera			

	Ĭ		<u> </u>		
Make:	Toyota	Model:	Surf		
Body Style:	Wagon	Year:	1996		
Rego No.:	EEJ293	Rego Expiry:	27 May 2026		
WoF Expiry:	11 Apr 2026	Odometer:	286,389 Kms		
Good No.:	27826996	VIN:	7A8H60G0707017828		
Next Service:	296, 393 Kms	Service History:	No		
Note: This report is not a warranty					

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

W = Significant scuffs S = ScratchR = RustC = Crack* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Plastic bull bar cover cracked.

LF guard mirror missing.

Minor crack in windscreen.

LH taillight cracked.

Conditions During Body Inspection	Dry				
Under Carriage and Under Bonnet Inspection Comments					

Engine oil leak.

Dirty/weak coolant.

Interior Comments			
Seats:	Average		
Carpets:	Average		
Panels:	Average		
Dashboard:	Average		

General Comments

Rear window only goes down via drivers switch but works both ways using the key in the tailgate.

High idle.

riigiridio.					
Road Condition	s During Test Drive	Dry			
Engine Timing Mechanism		Timing Chain			
Evidence of Cam Belt Replacement		Yes	No Km		
Inspected by:	Caleb Spicer Lee				
Published by:	Shanna Bullion				
Inspection Date:	02 Dec 2025				

I have read and understood
this condition guide:

NAME			

S	IG	N	Δ	Τl	П	R	F	