

Basic Condition Guide

•	Report ID:	27,829,514	Version:	1
	Created:	31 Dec 2025		

	ОК	Requires Attention	N/A
Engine		- Accessed in	14,71
Oil level	V		
Smoke & fumes	1		
Engine performance	~		
Noise	V		
Coolant condition	1		
Cooling performance	\(\tau \)		
Radiator / Hoses (visual)	/		
Transmission		L	
Operation	/	1	
Noise	/		
Clutch			
CV joints	/		
Wheel bearings	~		
Brakes		<u> </u>	
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	enth of	tvres)	
Left front	Сригог		7.0 mm
Right front			7.0 mm
Left rear			1.0 mm
Right rear			1.0 mm
Spare	N/A		
Suspension			
Suspension performance	1		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories		l .	
Head lights	~		
Tail lights	/		
Indicators			
Dashboard warning lights	✓ ✓		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	V		
Window winder RL	V		
Window winder RR	V		
Rear view mirrors	V		
Radio (basic test only)	V		
CD (basic test only)	V		
Number of keys	1	I	
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			
Reversing camera	1		
J		<u> </u>	


Make:	Mazda	Model:	Axela
Body Style:	Hatchback	Year:	2014
Rego No.:	QPR725	Rego Expiry:	22 Feb 2026
WoF Expiry:	18 Dec 2026	Odometer:	146,563 Kms
Good No.:	27829514	VIN:	7AT0C13JX24105772
Next Service:	156,550kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

ney				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Tow hook cover missing off left side of rear bumper. Scratches in left side sill. Crack in left side wing mirror cover & paint is worn on cover.

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comm	ents

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	

General Comments

Left side wing mirror will not adjust or retract when using wing mirror switch. Fin broken out & missing on centre right air vent. Left side parcel tray cord hook is broken off & missing on interior panel on tailgate.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Jason Young	
Published by:	Tiaan Pienaar	
Inspection Date:	31 Dec 2025	

I have	read	and	understo	ood
this co	nditi	on a	uide	

NAME			