

•	Report ID:	Report ID: 27,829,580		1
	Created:	04 Dec 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	<b>'</b>		
Smoke & fumes	1		
Engine performance	\( \frac{1}{V} \)		
Noise	/		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			l
Operation	·		
Noise	1		
Clutch			
CV joints	1		<del>ا</del>
Wheel bearings	· /		
Brakes			
Performance	<b>J</b>	<u> </u>	
Hand brake	1		
	donth of	turos)	
Tyres (lowest observed tread of Left front	lepth of	tyres)	4 mm
Right front			4 mm
Left rear			6 mm
Right rear			6 mm
Spare			
Suspension		1	
Suspension performance	•		
Steering performance	•	-	
Shock absorbers	/		
Air Conditioning / Heater		<u> </u>	
Operation	<b>'</b>		
Electrical / Accessories	1		
Head lights	<b>/</b>		
Tail lights	/		
Indicators	\( \sqrt{1} \)		
Dashboard warning lights			
Wipers (front & rear)	/		
Window winder FL	<b>'</b>		
Window winder FR	/		
Window winder RL	/		
Window winder RR	<b>/</b>		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)	/		
Number of keys	2		
Central locking	1		
Remote locking	<b>'</b>		
Sat. nav. (basic test only)			~
Sat. Hav. (Dasic test Offiy)			


Make:	Hyundai	Model:	Santa FE
Body Style:	SUV	Year:	2015
Rego No.:	JAH786	Rego Expiry:	24 Dec 2025
WoF Expiry:	23 Oct 2026	Odometer:	286,568 Kms
Good No.:	27829580	VIN:	KMHSU81XSFU442275
Next Service:	294,000	Service History:	Yes

### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

# Key

\* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram  $\,$ 

## **Body Inspection Comments**

Right side mirror housing scuff Left taillight condensation

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Rear differential leak

Front right mudflap damage

	Interior Comments		
Seats: drivers seat torn and has play		drivers seat torn and has play	
Carpets: Average		Average	
Panels: Average		Average	
	Dashboard:	Average	
	General Comments		

Partial service history

One key remote not operating

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Kilipati Mae	
Published by:	Kilipati Mae	
Inspection Date:	04 Dec 2025	

I have read and understood
this condition guide:

NAME			