

Basic Condition Guide

-	Report ID: 27,830,086		Version:	2
	Created:	03 Dec 2025		

Engine

Oil level

Noise

Smoke & fumes Engine performance

Coolant condition

Transmission

Wheel bearings

Brakes Performance Hand brake

Left front

Right front

Left rear

Right rear Spare

Suspension

Suspension performance

Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR

Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only)

Steering performance

Shock absorbers

Operation

Head lights

Tail lights Indicators

Operation Noise Clutch CV joints

Cooling performance

Radiator / Hoses (visual)

ОК

1

1

1

Yes

J

1

J

J

J

1

V

1 J

1

1

1

Tyres (lowest observed tread depth of tyres)

Requires

Attention

N/A

5 mm

5 mm

7 mm


8 mm

Make:	Ford	Model:	Ranger
Body Style:	Utility	Year:	2014
Rego No.:	HSD252	Rego Expiry:	15 Feb 2026
WoF Expiry:	29 Aug 2026	Odometer:	154,650 Kms
Good No.:	27830086	VIN:	MNAUMFF50EW295568
Next Service:	160,776kms	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

W = Significant scuffs S = ScratchR = RustC = Crack* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Wiper blade torn, missing front headlight bulb, both rear wheel cap missing, high stop light not working, gear knob plastic cover missing. Both front wheel play, underbody rust, engine oil leak, steering rock leak.

Conditions During Body Inspection	Wet	
Under Carriage and Under Bonnet Inspection Comments		

R tail light damage.

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	

General Comments

I have read and understood this condition guide:

Horn not working, steel wheel worn, both high beam not working, canopy paint defect, missing canopy key,

Road Conditions During Test Drive		Wet
Noau Condition	S During lest Drive	vvei
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Marlon Espena	
Published by:	Marlon Espena	
Inspection Date:	03 Dec 2025	

<u> </u>	neversing carriera		
IAME	SIGNATURE		