

Basic Condition Guide

Report ID:	Report ID: 27,843,905		2
Created:	19 Dec 2025		

Engine Oil level

Noise

Smoke & fumes Engine performance

Coolant condition Cooling performance Radiator / Hoses (visual)

Transmission

Wheel bearings

Tyres (lowest observed tread depth of tyres)

Operation Noise

Clutch CV joints

Brakes Performance Hand brake

Left front

Right front

Left rear

Right rear

Suspension

Suspension performance

Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

Steering performance

Shock absorbers

Operation

Head lights

Tail lights Indicators

Spare

ОК

V

1 1

Yes

J

1

1

1

J

1

1

1

1

1

1

1

1

Requires

Attention

N/A

9 mm

9 mm


4 mm

4 mm

Make:	Nissan	Model:	Navara	
Body Style:	Utility	Year:	2008	
Rego No.:	ELH183	Rego Expiry:	31 Dec 2025	
WoF Expiry:	03 Dec 2026	Odometer:	262,978 Kms	
Good No.:	27843905	VIN:	VSKCVAD40A0269961	
Next Service:	272970 kms	Service History:	No	
Note: This report is	not a warranty		·	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.				

Key

S = Scratch* = DecalsW = Significant scuffs R = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Both tail light cracked

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Leak inspected engine oil, rear diff, rust inspected underbody, not functioning number plate light L/r window master window switch, sign of damage/ wear/fading rear tyre driver seat, interior door panel, L/ v mirror.

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
General Comments		

Road Conditions During Test Drive		Dry
Engine Timing N	Mechanism	Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Marlon Espena	
Published by:	Marlon Espena	
Inspection Date:	19 Dec 2025	

inspection bate. To bee 20	520	neversing e	arricia		
		•			
I have read and understood					
this condition guide:	NAME	 SIGNATURE			