

Basic Condition Guide

•	Report ID: 27,859,458		Version:	1
	Created:	18 Dec 2025		

	OK	Requires Attention	
Engine			
Oil level	V		
Smoke & fumes	~		
Engine performance	1		
Noise	•		
Coolant condition	~		
Cooling performance	/		
Radiator / Hoses (visual)	1		
Transmission			
Operation	/		
Noise	1		
Clutch			/
CV joints	1		
Wheel bearings	1		
Brakes			
Performance	/		
Hand brake	~		
Tyres (lowest observed tread d	epth of	tvres)	
Left front			2.5 mm
Right front			3.2 mm
Left rear			2.8 mm
Right rear			3.8 mm
Spare	Yes		
Suspension			
Suspension performance	1		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	/		
Tail lights	~		
Indicators	/		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL			
Window winder FR	V		
Window winder RL	1		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			/
Number of keys	1		
Central locking	/		
Remote locking	/		
	1		
Sat. nav. (basic test only) Reversing camera	<i>'</i>		V


Make:	Nissan	Model:	Bluebird
Body Style:	Sedan	Year:	2007
Rego No.:	KBZ461	Rego Expiry:	19 Mar 2026
WoF Expiry:	01 Jan 2027	Odometer:	89,944 Kms
Good No.:	27859458	VIN:	7AT0DH1EX16064212
Next Service:	100,000 Kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

key				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D - Dont	DT - Paint defect	D — Din dont	SC - Stone Chins	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Surface rust in boot jamb Cracks in wheel hub caps Front left wing mirror damaged

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

2WD

Surface rust in engine bay and on underside of vehicle

	Interior Comments		
	Seats: Wear on drivers seat		
	Carpets: Wear on drivers floor mat		
Panels: Good		Good	
Dashboard: Trim missing from centre left side air vent		Trim missing from centre left side air vent	
	Conoral Comments		

Road Conditions During Test Drive Dry Engine Timing Mechanism Timing Chain Evidence of Cam Belt Replacement Yes No Kms Inspected by: Hoani Saunders Published by: Jayson Rodriguez Inspection Date: 15 Dec 2025

П	nave	read	and	unde	rstood
tł	nis co	nditi	on a	uide	

NAME			