

Report ID:	27,879,182	Version:	1
Created:	23 Dec 2025		


	ОК	Requires Attention	N/A
Engine	<u> </u>	/ (ctcirtioii	14/71
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise	V V		
Coolant condition			
Cooling performance	V		
Radiator / Hoses (visual)	/		
Transmission		<u> </u>	
Operation	1		
Noise	/		
Clutch	V V		
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread de	epth of	tyres)	
Left front			2 mm
Right front			2 mm
Left rear			2 mm
Right rear			2 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	V V		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL			/
Window winder RR			/
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)	/		
Number of keys	1		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			/
Reversing camera	/		

Make:	Mazda	Model:	Bt-50
Body Style:	Utility	Year:	2014
Rego No.:	RNM271	Rego Expiry:	15 Jun 2026
WoF Expiry:	16 Dec 2026	Odometer:	172,553 Kms
Good No.:	27879182	VIN:	MM0UP0YF100225660
Next Service:	no sticker	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

W = Significant scuffs S = ScratchR = RustC = Crack* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Front bumper misaligned

Condensation in both reverse lights and left taillight

Holes and rust in ute tray

Missing rear make and model badges

Under Carriage and Under Bonnet Inspection Co		
Conditions During Body Inspection	Dry	

Underbody sealed

Right sill dented

Interior Comments			
Seats:	driver seat minor tear		
Carpets:	Carpets: Good		
Panels:	Good		
Dashboard: Good			
General Comn	General Comments		

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Sione Mae	
Published by:	Sione Mae	
Inspection Date:	23 Dec 2025	

I hav	ve read	and	understood
thic	conditi	on a	uide.

NAME			