

Basic Condition Guide

•	Report ID:	27,884,280	Version:	1
	Created:	24 Dec 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	V		
Smoke & fumes	/		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	/		
Clutch			~
CV joints		~	
Wheel bearings	~		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			6 mm
Right front			6 mm
Left rear			6 mm
Right rear			7 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	V		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			
Number of keys	2		
Central locking	/		
Remote locking			'
Sat. nav. (basic test only)			
Reversing camera			V


Make:	Toyota	Model:	Hilux
Body Style:	Wagon	Year:	1994
Rego No.:	CLJ556	Rego Expiry:	29 Mar 2026
WoF Expiry:	19 May 2026	Odometer:	184,462 Kms
Good No.:	27884280	VIN:	7A8H60G0704061811
Next Service:	187,000kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

ĸey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

F/L park light cracked & not working.

F/R indicator lens cracked.

Aerial broken.

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Left inner CV boot split.

Major engine oil leaks.

Interior Comments		
Seats: Rips on drivers seat.		
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
General Comments		

4x4 diesel auto SUV.

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		✓ Yes	No	97,982 Kms
Inspected by:	Daryll Timms			
Published by:	Daryll Timms			
Inspection Date:	24 Dec 2025			

I have read and understood
this condition guide:

NAME			

SI	GN	AT	URF	