

Basic Condition Guide

•	Report ID: 27,886,190		Version:	1
	Created:	28 Dec 2025		

	,	Requires	
	OK	Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	/		
Clutch			1
CV joints		~	
Wheel bearings	/		
Brakes			
Performance	V		
Hand brake	/		
Tyres (lowest observed tread	depth of	tyres)	
Left front	T [']		2 mm
Right front			3 mm
Left rear			3 mm
Right rear			3 mm
Spare	Yes		
Suspension			
Suspension performance	· /		
Steering performance		· /	
Shock absorbers	1	<u> </u>	
Air Conditioning / Heater			<u> </u>
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		Ι
Operation Electrical / Accessories			<u> </u>
	1		
Head lights	V		
Tail lights		-	
Indicators	/		
Dashboard warning lights	V		
Wipers (front & rear)	V		
Window winder FL	/		
Window winder FR	/		
Window winder RL			
Window winder RR	/	-	
Rear view mirrors			
Radio (basic test only)		'	
CD (basic test only)		/	
Number of keys	1		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			1
Sat. Hav. (Dasic test Offly)			


Make: Mazda		Model:	Atenza
Body Style:	Wagon	Year:	2010
Rego No.:	LST704	Rego Expiry:	23 Apr 2026
WoF Expiry:	01 Dec 2026	Odometer:	176,188 Kms
Good No.:	27886190	VIN:	7AT0C139X18202010
Next Service:	183900	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = ScratchR = RustC = Crack* = Decals W = Significant scuffs D = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Paint rough

Fog lights not working

R fog light cracked

Front bumper misaligned

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Front plastic panels zip tied

F/R CV boot major fluid leak requires further investigation

Engine oil seepage

Interior Comments		
Seats:	Good	
Carpets:	worn drivers floor	
Panels:	Good	
Dashboard:	cracked & sticky- headunit not work- worn st wheel	

General Comments

Wing mirror fold in button doesn't work, L Wing mirror button doesn't adjust

Push button start button cracked open

Steering veers to right & shutters

R/Fog light panel loose				
F	Road Conditions During Test Drive		Dry	
E	Engine Timing Mechanism		Timing Chain	
E	Evidence of Cam Belt Replacement		Yes No Kms	
I	nspected by:	Phillip Russel-Waimotu		
F	Published by:	Phillip Russel-Waimotu		
ı	nspection Date:	28 Dec 2025		

I have read and understood
this condition guide:

NAME			