Turners

Basic Vehicle Condition Guide

Make: Suzuki	**Model:** Swift	**Body Style:** Hatchback
Year: 2008	**Registration:** ELH349	**Reg Expiry:** 07 Sep 2019
WoF Expiry: 05 Feb 2020	**Odometer:** 171,622 Kms	**Good No:** 18874368
VIN: JSAEZC31S00201755	**Next Service:** 181000	**Service History:** No

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs

Diagram labels: D SC, S SC, W, S D SC, S, SC, PT P SC, SC, W, W, S, S

Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments
Headlights faded
Windscreen chips

Condition	Pass	Fail	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Performance	✔		
Noise	✔		
Cooling System			
Coolant condition	✔		
Performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch	✔		
CV joints	✔		
Wheel bearings	✔		
Brakes			
Performance	✔		
Hand Brake	✔		

Tyres (lowest observed tread depth of tyres)

Left front	4.0	mm
Right front	4.0	mm
Left rear	4.0	mm
Right rear	4.0	mm
Spare	N/A	

Condition	Pass	Fail	N/A
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation	✔		
Electrical / Accessories			
Head lights	✔		
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL	✔		
Window winder FR	✔		
Window winder RL	✔		
Window winder RR	✔		
Rear view mirrors	✔		
Radio (basic test only)	✔		
CD (basic test only)	✔		
Number of keys	2		
Central locking	✔		
Remote locking	✔		
Sat. Nav. (basic test only)			✔
Reversing camera			✔

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments

Seats	drivers seat worn
Carpets	Average
Panels	Average
Dashboard	Average

General Comments
second key remote is not working

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain
Evidence of Cam Belt Replacement: Not Applicable   Kms:

Inspected by: Hamish McDonald

Date: 24 Jan 2019

I have read and understood this condition guide.   Name: ………………………………………   Signature: ………………………………………