Turners

Basic Vehicle Condition Guide

Report ID: 19,502,416
Version: 1
Created: 28 May 2019

|		
Make: Volkswagen	**Model:** Passat	**Body Style:** Wagon
Year: 2007	**Registration:** KGF988	**Reg Expiry:** 14 Jun 2019
WoF Expiry: 19 Oct 2019	**Odometer:** 66,965 Kms	**Good No:** 19502416
VIN: WVWZZZ3CZ7E22085	**Next Service:** 74514	**Service History:** No

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs

SC
PT SC

Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments

	Pass	Fail	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Performance	✔		
Noise	✔		
Cooling System			
Coolant condition	✔		
Performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch			✔
CV joints	✔		
Wheel bearings	✔		
Brakes			
Performance	✔		
Hand Brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front	5		mm
Right front	5		mm
Left rear	6		mm
Right rear	6		mm
Spare	Yes		
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation	✔		
Electrical / Accessories			
Head lights	✔		
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL	✔		
Window winder FR	✔		
Window winder RL	✔		
Window winder RR	✔		
Rear view mirrors	✔		
Radio (basic test only)	✔		
CD (basic test only)			✔
Number of keys	2		
Central locking	✔		
Remote locking	✔		
Sat. Nav. (basic test only)			✔
Reversing camera			✔

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

LF cv joint leaking grease

Interior Comments

Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

2wd
Head unit pocket misaligned
One remote key cannot unlock

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No   Kms:

Inspected by: Bobby Zhong

Date: 28 May 2019

I have read and understood this condition guide.   Name: ………………………………………   Signature: …………………………………