

Certificate of Fitness

DDU496

Plate: DDU496
 2006 MITSUBISHI CANTER FE122W5 WHITE
 Owner: SIONE TOPENI13/02/2006
 Class: NB
 Fuel: DIESEL
 ODO Reading: 291462 (K)
 Last Inspection: PASSED

Inspection Expiry: 25/02/2015
 Insp. Freq. (months): 6

No of Axles: 2
 VIN Location: L/F CHASSIS
 Last Hubo Serial No : 2/635994

Reg Expiry	8/08/2016
AVIC No.	VT/35
Order Number	
WoF/CoF Fee \$	
Receipt Number	16951892
Odometer Reading	306754
Hubo Reading	16501
Hubo Number	2/635994
Recheck Fee \$	
Recheck Odo	
Recheck Hubo	
Tractor/Trailer Reg No.	
TSL	
Tare	
Max Air Pressure	
Apps/ Pressure	
Recovery Time	
Auxiliary Device	
Warning Device	

VIN/ Chassis No	JLAFE649E0K N40116	Product Code	G2	POS	Paid	LATIS	ISS
Initial Inspection	Fail	Lane No.	2	Recheck Inspection		Lane No.	
Inspector ID	TJR/	Inspector ID		Inspector sign		Inspector Date	
Insp. sign	JR	Date	31/01/2017	NZTA Auth No.		Label No.	
NZ Standards				5413	<input type="checkbox"/>	5444	<input type="checkbox"/>
				5446	<input type="checkbox"/>	5450	<input type="checkbox"/>
				5451	<input type="checkbox"/>	5467	<input type="checkbox"/>
				NZHVCB	<input type="checkbox"/>	Other	
Checklist:	CHTK	Rev	4	This check sheet does not constitute a Warrant of Fitness or Certificate of Fitness. Rechecks must take place within 28 days of the original inspection. After the 28 days a new inspection must be carried out and a new fee paid. Last date for recheck is 28/02/2017			
Detailed checklist available to customer on request							

WRN 5	Tyre Tread		TJR/ Service Brake						TJR/ Park Brake				Air System	
	L	R	Initial 61 %			Recheck % or Static P/F			Initial Static Pass		Recheck % or Static P/F		Max Air Pressure	
Axle	Left/Weight	Right %	Max % Imbalance	Left/Weight	Right %	Max % Imbalance	Left/Weight	Right %	Left/Weight	Right %	Left/Weight	Right %	Apps/ Pressure	
1	7	4	1850	73	9									
2	4	2	3100	55	18									
3														
4														
5														

Category Description	Pass/Fail	Inspector ID	Fault Code	Reasons Vehicle Failed Its Inspection
Front Lamps	Pass	WRN5	WTA6	Left Front Wheel Hub Binding
Lighting	Pass	WRN5	UWA7	Right Front Wheel Bearing Binding
Vehicle Raised	Fail	TJR/	VLP1	TSL Number Not Presented
Exterior	Fail	TJR/	ELI1	All Deck Damaged
Under Bonnet	Pass	TJR/	EON2	Front Deck Headboard Corrosion
Underbody	Fail	WRN5	MEI1	All Excessive Visible Exhaust Smoke To Improve
Air System	Pass	TJR/	WFO4	Left Mudflaps Missing
Interior	Pass	TJR/	USW2	Axle 1 Spring Shackle Bush Worn Right
			SDW1	Rearward Steering Draglink Joints Play Adjustment Required
			WTW7	Right Front Tyre Tread Inner Edge Worn

Notes
RUC purchase required. Check current RUC label is displayed.
Axle 1 Spring Shackle Bush Requires Attention Soon Left