

Vehicle Service History Report

SPECIALISED FLEET SERVICING

Printed: 27/09/16 10:02
From: 1/12/15 to 27/09/16

Page: 1

2006 IVECO STRALIS 749

Owned by CARDINAL LOGISTICS

Reg. No: DLG964

Invoice No:8171-1	Date: 31/08/16	Reading: 365,115	Job Description: LIST OF REPAIRS
--------------------------	-----------------------	-------------------------	---

22/08/2016

inspect power steering fault

replace l/h headlight

Labour(hours)	1.00
---------------	------

Invoice No:8087-1	Date: 31/07/16	Reading: 365,115	Job Description: ATTEND TO BREAKDOWN
--------------------------	-----------------------	-------------------------	---

CONSUMABLES	1.00
-------------	------

Labour(hours)	3.00
---------------	------

26/07/2016

repair air leak

Travel to breakdown found air hose burst going to tank.

remove and replace 1m section of hose.

travel back to workshop

Invoice No:8064-1	Date: 29/07/16	Reading: 365,115	Job Description: LIST OF REPAIRS
--------------------------	-----------------------	-------------------------	---

boost sensor	1.00
--------------	------

Labour(hours)	8.50
---------------	------

18/07/2016

pick truck from yard

disconnect trailer

diagnose fault

tighten loose airline

test truck

replace turbo pressure sensor

grease turntable

fix leaking hose at rear of cab

drop off to yard

edc fault

GREASE TOTAL	1.00
--------------	------

CONSUMABLES	1.00
-------------	------

Invoice No:8053-1	Date: 29/07/16	Reading: 365,115	Job Description: LIST OF REPAIRS
--------------------------	-----------------------	-------------------------	---

13/07/2016

travel to yard

inspect not starting

found transmission stuck in gear and no air

plumb in air to build up system

Transmission in neutral, start truck

Vehicle Service History Report

SPECIALISED FLEET SERVICING

Printed: 27/09/16 10:02
From: 1/12/15 to 27/09/16

Page: 2

2006 IVECO STRALIS 749

Owned by CARDINAL LOGISTICS

Reg. No: DLG964

top up p/steering fluid	
Travel back to workshop remove and replace leaking	
power steering hose	
push lock fitting	2.00
full synthetic oil	1.00
Hose	1.00
Labour(hours)	9.00

Invoice No:8046-1	Date: 29/07/16	Reading: 365,115	Job Description: AIRLEAK
--------------------------	-----------------------	-------------------------	---------------------------------

11/07/2016	
inspect airleak	
found air shock leaking	
plug in lap top	
clear all codes	
replace blown bulbs	
BULB - H3	2.00
Connect to diagnosing software	1.00
INDICATOR BULB	1.00
Labour(hours)	8.50

Invoice No:8039-1	Date: 29/07/16	Reading: 1,385,531	Job Description: B SERVICE
--------------------------	-----------------------	---------------------------	-----------------------------------

6MM JOINER	3.00
air dryer filter	1.00
Labour(hours)	27.17

NOTE:

We will send you a reminder card for your next COF inspection and
service dates

We value and thank you for your business.

CONSUMABLES	2.00
GREASE TOTAL	1.00
ENGINE OIL	32.00
OIL FILTER IVECO	2.00
FUEL FILTER	1.00
FUEL FILTER	1.00
Light - front indicator	1.00
REFLECTOR	1.00
relay valve	1.00

08/07/2016

Pick up vehicle from yard

Vehicle Service History Report

SPECIALISED FLEET SERVICING

Printed: 27/09/16 10:02
From: 1/12/15 to 27/09/16

Page: 3

2006 IVECO STRALIS 749

Owned by CARDINAL LOGISTICS

Reg. No: DLG964

Air leaking from rear of cab
Locate faulty hose fit 6mm joiners
Bring back to workshop
Carry out B service
Remove and replace all Fuel filters
Drain and replace oil and filters
Grease and adjust all brakes
Check all fluid levels
Check all electrical circuits for operation
Check All wheel bearing play and Kingpin play
Check Air system operations
Inspect chassis area for cracks
Used 32lt engine oil
Check all wiring
Refit drivers mirror
Locate and repair damaged wiring
Replace 15a fuse
Replace air drier filter
Also found valve at air dryer unit leaking
remove and replace
replace broken front l/h lights
Remount rear light assembly [both sides]
Deliver back to yard
Inspect suspension system

Invoice No:8027-1	Date: 29/07/16	Reading: 365,115	Job Description: AIRLEAK
--------------------------	-----------------------	-------------------------	---------------------------------

05/07/2016

inspect airleaks

Travel to yard

Found all hoses are hard and brittle

Repair all air hoses

Bring back to workshop

plug in laptop, check out faults

CONSUMABLES

1.00

Connect to diagnosing software

1.00

6mm air hose

3.00

6mm pushlock fitting - union

6.00

12mm air hose

4.00

Labour(hours)

6.00

Vehicle Service History Report

SPECIALISED FLEET SERVICING

Printed: 27/09/16 10:02
From: 1/12/15 to 27/09/16

Page: 4

2006 IVECO STRALIS 749

Owned by CARDINAL LOGISTICS

Reg. No: DLG964

Invoice No:7974-1	Date: 30/06/16	Reading: 365,115	Job Description: ATTEND TO BREAKDOWN
--------------------------	-----------------------	-------------------------	---

14/06/2016

Travel to Neilson St Onehunga in peak hour traffic

Vehicle not starting

Remove fuel filter and fill with fuel

Bleed fuel system and start

Run for 10 min and switch off

Start engine okay

Return to workshop

Traveling to breakdown	40.00
------------------------	-------

fuel Filter	1.00
-------------	------

Labour(hours)	3.00
---------------	------

Invoice No:7961-1	Date: 30/06/16	Reading: 365,115	Job Description: LIST OF REPAIRS
--------------------------	-----------------------	-------------------------	---

CONSUMABLES	1.00
-------------	------

Labour(hours)	5.00
---------------	------

08/06/2016

Pick up truck

inspect airleak

found burst airline inside r/h chassis rail

cut all calbe ties

cut and fit a new section of plastic hose

Invoice No:7913-1	Date: 31/05/16	Reading: 365,115	Job Description: AIRLEAK
--------------------------	-----------------------	-------------------------	---------------------------------

reverse gear.replace cover and secure.deliver truck back to yard.

AMBER BULBS 24V21	1.00
-------------------	------

4 way protection valve	1.00
------------------------	------

air dryer repair kit	1.00
----------------------	------

laptop diagnostic charge	1.00
--------------------------	------

Cartridge Air Filter	1.00
----------------------	------

Labour(hours)	29.00
---------------	-------

24/05/2016

airleak

bad airleak from 4/way protection valve.remove air dryer valve

assembly from truck.separate 4/way protection valve from air

dryer.strip air dryer and clean and rekit and change air dryer

filter.strip 4/way protection valve and found 3 check valve

discs torn.no repair kit available so sourced new valve.fit to

air dryer and refit to truck.reattach airlines and build up air

Vehicle Service History Report

SPECIALISED FLEET SERVICING

Printed: 27/09/16 10:02
From: 1/12/15 to 27/09/16

Page: 5

2006 IVECO STRALIS 749

Owned by CARDINAL LOGISTICS

Reg. No: DLG964

pressure.found exhaust brake airline rubbed through.repair
airline and recheck.all ok.no airleaks.fault find on electronic
dash faults as gearbox not changing in automatic mode.attach
computer and clear all faults.gearbox faults still present.check
fuses and found ebs blown fuse.replace fuse and clear
faults.roadtest truck.now changing in auto mode but not able to
select low reverse gear.remove electronic gear shift cover and
inspect.found relay attached to shift module not secured properly
and loose in connectin.push relay in properly and secure to
mounting slot correctly.able to then select low and high

Invoice No:7895-1	Date: 31/05/16	Reading: 365,115	Job Description: MUDGAURD REPLACEMENT
--------------------------	-----------------------	-------------------------	--

Labour(hours)	16.50
coolant.deliver truck back to yard.	
mudguard poles	2.00
plastic header coolant tank	1.00
antifreeze concentrate	4.00
Mudguards	4.00
CONSUMABLES	2.00
Mudgaurd Brackets	12.00

18/05/2016

Replace all mudguards
setup all heights to suit container set up
pick up truck from yard.remove all mudguards and remove two
bent poles.replace bent poles.install new mudguards and set up
heights lower than original mudguards to carry containers.drill
and fit mudguard supports to mudguards and secure
mudguards.adjust support poles for height and secure poles.
check for coolant leak and found coolant header tank leaking from
plastic seam.source new tank and fit.topup cooling system with

Invoice No:7877-1	Date: 30/05/16	Reading: 365,115	Job Description: MUDGAURD REPLACEMENT
--------------------------	-----------------------	-------------------------	--

Order 4 new gaurds and brackets	
CONSUMABLES	2.00
Labour(hours)	3.00

13/05/2016

3rd axle mudgaurd damaged

Trying to source new mudgaurd none available

Fit 2nd hand gaurd to keep vehicle mobile

Vehicle Service History Report

SPECIALISED FLEET SERVICING

Printed: 27/09/16 10:02
From: 1/12/15 to 27/09/16

Page: 6

2006 IVECO STRALIS 749

Owned by CARDINAL LOGISTICS

Reg. No: DLG964

Heat up and straighten gaurd bracket [accident damage]

Invoice No:7819-1	Date: 30/04/16	Reading: 365,115	Job Description: COF INSPECTION
--------------------------	-----------------------	-------------------------	--

Labour(hours)	21.17
GREASE TOTAL	1.00
7 inch Air Ram	1.00
VCA / DLG964	1.00
COF / DLG964	1.00
shock bolt	1.00
Red Reflector	1.00
hose	1.00

20/04/2016

Carry out Pre Cof inspection on truck

Check all electrical light conditions and operation

Jack up front axle wheels and check wheel bearings and adjust

brakes,also adjust rear brakes

Check driveshafts,and suspension components

Check chassis mounts, and bolts

Grease unit.

reflector

Carry out 5th certification

Remove 5th wheel,inspect for cracks,inspect jaw conditions

Test operation and adjustment and adjust if needed.

Note:COF EXPIRY DATE: 21/10/2016 - HUBO:253059

NOTE:

We will send a reminder card for your next COF inspections

We value and thank you for your business.

CONSUMABLES	2.00
-------------	------

Invoice No:7743-1	Date: 31/03/16	Reading: 222,955	Job Description: ELECTRICAL FAULT
--------------------------	-----------------------	-------------------------	--

CONSUMABLES	2.00
-------------	------

Labour(hours)	4.00
---------------	------

22/03/2016

inspect why electrical for eroad

Found suzi leads wasnt corectly wired to code

also found number 5 pin no power supply at truck

also a poor earth wire

Wire up power supply with fuse link

wire up earth wire