

Basic Vehicle Condition Guide

Report ID: 17,356,539

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Suspension performance Steering performance

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

Created: 20 Feb 2018

Fail

1

N/A

mm

mm

mm

 mm

5

5

4

1

1

/

1

1

1

1

1

~

1

Yes

Pass

~

/


1

Tyres (lowest observed tread depth of tyres)

Make: Model: **Body Style:** Nissan Vanette Van Year: Registration: **Reg Expiry:** 2,009 **GZK339** 29 Jan 2019 **WoF Expiry: Odometer: Good No:** 04 Feb 2018 201,306 Kms 17356539 VIN: **Next Service: Service History:** 7AT0DH19X13204415 204100 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips front screen. Right centre pillar dented. Drivers door monsoon shield missing. Number plate light not working. Drivers door glass tends to get stuck in open position.

Conditions During Body Inspection: Wet

<u>Under Carriage & Under Bonnet Inspection Comments</u>

Interior Comments			
Seats	Poor		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Engine check light and DPF warning light on. Thump when brakes applied further investigation required. Trans thumps when changing. Engine seems to lack power.

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** Kms: Nο

I have read and understood this condition guide.

20 Feb 2018 Inspected by: Brian Hill Date:

Name:	 Signature:	