

Report ID: 17,401,627

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Suspension performance

Steering performance

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Shock absorbers Air Conditioning / Heater

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

Created: 09 Apr 2018

Fail

N/A

1

mm

mm

mm

 mm

2

3

5

1

1

/

1

V

2

Yes

Pass

1

V

V


1

Tyres (lowest observed tread depth of tyres)

Make: Model: **Body Style:** SUV Toyota Highlander Year: Registration: **Reg Expiry:** 2,007 **DRZ126** 16 Apr 2018 **WoF Expiry: Odometer: Good No:** 08 Jun 2018 239,481 Kms 17401627 VIN: **Next Service: Service History:** JTEHP21A700166951 240000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Stonechips on windscreen. Headlamps need buffing. Rear bumper not secure. Paint damage on front bumper. All seats have marks. No wheel brace. RF seat is worn. Remote locking not working.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Coolant additive concentration below manufactures recomended level suggest coolant change. Rear swaybar bushes are worn.

Interior Comme	<u>nts</u>
Seats	Poor
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

Inspected by:

Power steering pump is worn, needs replacing and fluid flushing. Drives ok.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Roger King

Evidence of Cam Belt Replacement: Nο

I have read and understood this condition guide.

		Sat. Nav. (basic test only)		~
Kms:		Reversing camera		~
	Date: 09 Apr 201	8		
Name:		Signature:		