

Report ID: 17,896,218 Version: 1 22 May 2018 Created:

Make:	-	Model		Dody Crata			Deco	۲-۱	N1 / A
	Toyota	Model:	Landcruiser	Body Style:	Wagon	Engino	Pass	Fail	N/A
Year: WoF Expiry:	1,996	Registration: Odometer:	DDN507	Reg Expiry: Good No:	21 Jun 2018	Engine Oil level			T
VIN:	22 Jun 2018		273,689 Kms	Service History	17896218		~		<u> </u>
viiv.	7A8H60H0705021726	wext Service.		Service History	/ No	Smoke & fumes	~		<u> </u>
Note: This re	port is not a warranty					Performance	~		
	a guide only. Conside					Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition		~	
Key:	S SC		SC SC		SC	Performance	~		
S = scratch		(0)		$\neq (0)$	\checkmark	Radiator / Hoses (visual)	~		
D = dent			\leftarrow		All IS	Transmission		1	
R = rust	s sc 96				HUY	Operation	~		<u> </u>
PT = paint def	ect				SC	Noise	~		<u> </u>
C = crack	III					Clutch			~
P = pin dent * = decals	sc dl				THE	CV joints	~		
SC = stone chi	ps U	10		10		Wheel bearings	~		
W = significant scuffs						Brakes			
-	SC	N	SC S SC		S SC	Performance		~	<u> </u>
Body Inst	pection Comments	Note: son	ne defects & blemis	hes may not be disp	layed in the diagram	Hand Brake	~		
Aerial not working. Stonechips and wiper scratch on windscreen. RH mirror damaged. Taillights and						Tyres (lowest observed tread depth of tyres)			es)
numberplate lights not working.						Left front	5 mm		
Console lid broken. Gear indicator by gear lever is damaged. Steering wheel rattles when turned. Heater fan is noisy. Tray under heater controls is damaged.						Right front		5	mm
		5				Left rear	1	.8	mm
Conditions During Body Inspection: Dry						Right rear	1	1.4	
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	corrosion on it. Coolant					Suspension performance	~		
	lly water no additive, su area. Chassis and suspe					Steering performance	~		
				- J		Shock absorbers	~		
						Air Conditioning / Heater	1		1
						Operation	~		
Interior Comments						Electrical / Accessories	1		4
Seats	Average	Average					~		
	Average					Tail lights		~	1
Carpets	, weinge					Indicators	~		1
Panels	Average					Dashboard warning lights	~		1
	, Average					Wipers (front & rear)	~		+
Dashboa	rd Average					Window winder FL	~		+
L	1					Window winder FR	~		+
General (<u>Comments</u>					Window winder RL	~		+
Rust under RF, LR and RR tread plates on sills. All flares have rust marks on body. Tailgate hinges worn. Rust					Window winder RR	~		+	
on floor in cargo area. Both front seats are worn. RR monsoon on rear seat. Wear on RF seatbelt and door card. CD player not						Rear view mirrors		~	+
working.						Radio (basic test only)	~	-	+
						CD (basic test only)	-	~	
						Number of keys	2	-	1
Pood Com	ditions During To					Central locking	2		T
	ditions During Test		Dry			Remote locking	-		~
Engine Ti	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)			-
-	of Cam Belt Replac		10	Kms:		Reversing camera			~ ~
Inspecte	d by: Roger King					Date: 22 May 20)18		
have read	and understood th	is condition o	juide. Name	2:		Signature:			