

Report ID: 18,265,936

Version:

Engine Oil level Smoke & fumes

Noise

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 10 Jul 2018

Pass

~

/

/

V

1

Tyres (lowest observed tread depth of tyres)

N/A

~

mm

mm

mm

 mm

1

~

~

4

5

5

1

/

/

/

1

1

2


Yes

Fail

Make:	Mercedes-Benz	Model:	CLK	Body Style:	Sports Car
Year:	2,000	Registration:	HQJ327	Reg Expiry:	23 Mar 2018
WoF Expiry:	12 Dec 2018	Odometer:	134,821 Kms	Good No:	18265936
VIN:	WDB2083482F170652	Next Service:	0	Service Histor	y: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comme	<u>ents</u>
Seats	wear and tear, worn, electrics not working on seats
Carpets	Good
Panels	speaker broken off drivers door ,
Dashboard	Good

General Comments

Automatic gear stick set needs to be looked at broken has a bolt in it so move the bolt up and down to get it out of drive and into park, stereo needs a code to work,

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Kms: Not Applicable

Inspected by: Donovan Matara

Signature:	
 Signature.	

10 Jul 2018 Date: I have read and understood this condition guide. Name: