

Report ID: 18,294,869

**Pass** 

1

~

V

1

Version: 3

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Left front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Suspension performance Steering performance

Spare

Right front

Created: 11 Sep 2018

Fail

~

N/A

1

mm

mm

mm

mm

6.1

1.5

2.6

1

/

/

1

1

1

~


~

Yes

Make: Model: **Body Style:** Hatchback Volkswagen Golf Year: Registration: **Reg Expiry:** 2,005 **GBR921** 22 Mar 2019 **WoF Expiry: Odometer: Good No:** 18294869 27 Feb 2019 174,556 Kms VIN: **Next Service: Service History:** WVWZZZ1KZ5U02227 170,348 No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

**Under Carriage & Under Bonnet Inspection Comments** 

Engine oil leak

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Average		

Dry

## **General Comments**

Inspected by:

Engine noise - intermittent

Central locking not working on drivers side doors.

**Road Conditions During Test Drive:** Dry

**Engine Timing Mechanism:** Cambelt

lan Dunn

I have read and understood this condition guide.

**Evidence of Cam Belt Replacement:** Kms: No

> Date: 10 Aug 2018

lame:	 Signature:	