

Report ID: 18,489,710 Version: 2 Created: 02 Oct 2018

| Make: | Toyota | Model: | Harrier | Body Style: | SUV | | Pass | Fail | N/A |
|--|--------------------|---------------|-------------|----------------|---------------|--|----------|----------|-----|
| Year: | 2000 | Registration: | CRD738 | Reg Expiry: | 16 Jul 2019 | Engine | | | L |
| WoF Expiry: | 16 Aug 2019 | Odometer: | 203,300 Kms | Good No: | 18489710 | Oil level | ~ | | |
| VIN: | 7A8H6340705067206 | Next Service: | 205000 | Service Histor | | Smoke & fumes | ~ | | |
| | 770110340703007200 | | 203000 | | 7 . NO | Performance | • • | | |
| Note: This report is not a warranty | | | | | | Noise | • • | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Coolant condition | | | 1 |
| | | _ | | | | Performance | ~ | | |
| Key: | sc | -0 | sc sc | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | | | | | | | | | |
| R = rust | | | | | | Operation | ~ | | |
| PT = paint def C = crack | ect | | | + | SC | Noise Clutch | ~ | | |
| P = pin dent | Ho | | | | | | | | ~ |
| * = decals SC P/P | | | | | | CV joints | ~ | | |
| SC = stone chips | | | | | | Wheel bearings | ~ | | |
| W = significant scuffs | | | | | | Brakes | | | |
| | | | | | | Performance | ~ | | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | Hand Brake | ~ | <u> </u> | |
| Stone chips front screen. Drivers door rubber worn. Unable to adjust right mirror. | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | Left front | 2.0 mm | | - | |
| | | | | | | Right front | 3 | .0 | mm |
| | | | | | | Left rear | 4 | .0 | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear | 5 | .0 | mm |
| | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | 1 | |
| Interior Comments | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | 1 | |
| Seats | Good | | | | | Head lights | ~ | | |
| Carpets | Good | | | | | Tail lights | ~ | | |
| | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| Dashboa | Good | | | | | Wipers (front & rear) | ~ | | |
| Dastibua | | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General Comments New cam belt just fitted | | | | | | Window winder RL | ~ | | |
| New cam b | elt just fitted | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | | ~ | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | | | - | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Cambelt | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: Y | 'es | Kms: 20 | 02,620 | Reversing camera | | | ~ |
| | | | | | | | | | |
| Inspected by: Brian Hill Date: 30 Aug 2018 | | | | | | | | | |
| I have read and understood this condition guide. Name: | | | | | | | | | |