

Basic Vehicle Condition Guide

Report ID: 18,619,845

Pass

1

~

/

1

Tyres (lowest observed tread depth of tyres)

Version: 3

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Suspension performance

Spare

Coolant condition
Performance

Radiator / Hoses (visual)

Created: 19 Nov 2018

Fail

N/A

/

mm

mm

mm

 mm

7.2

6.5


5.7

Yes

Make: Model: Holden Commodore **Body Style:** Sedan Year: 2013 Registration: GZU226 **Reg Expiry:** 21 Jul 2019 WoF Expiry: **Odometer:** 23 Jul 2019 201,918 Kms **Good No:** 18619845 VIN: 6G1EK5E58CL719738 **Next Service:** 200,000kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

- Hole in right side of back rest on drivers seat.
- 2 x R/T aerial bases fitted to roof & hole in roof where wires have been for light bar.- Crack in lower front bumper.
- Stone chips in windscreen.
- Plastic wheel nut covers missing off left rear wheel.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

- Front brake disc/rotors worn.
- Front muffler has small leak.
- Engine oil level on low mark on dip stick.
- Check engine light is on.

Interior Comments			
Seats	Average		
Carpets	Good		
Panels	Average		
Dashboard	Good		

General Comments

Ex nz police vehicle.

Inspected by:

- Base of cup holder missing in centre console & metal plate fitted over pocket, under heater controls.
- 4 x bolt hole in left side foot well, by centre console.

Jason Young

- 3 x screw holes in dashboard.
- Front radio speakers not working & audio/trip button not working on steering wheel.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain
Evidence of Cam Belt Replacement: Not Applicable Kms:

Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater		•	
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~
Date: 01 Nov 20	18		
Signature:			

have read and understood this condition guide.	Name:	Signature: