

Report ID: 18,862,139 Version: 1 Created: 11 Jan 2019

Make:	Audi	Model:	C /	Body Style:	Wagan		Daca	Eail	NI/A
Make: Year:	Audi 2005		S4 JDK369		Wagon	Engine	Pass	Fail	N/A
WoF Expiry:		Odometer:		Reg Expiry: Good No:	18862139	Oil level	1		T
VIN:	WAUZZZ8E75A52914		140,386 Kms	Service Histor		Smoke & fumes		~	
VIIN.	WAUZZZ8E75A52914	Next Service.	130,100kms	Service Histor	r y: No		~		
Note: This re	port is not a warranty					Performance	~		
	a guide only. Conside					Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
Key:			S PT	S		Performance	~		
S = scratch	~	(0)		$\overline{(0)}$	\checkmark	Radiator / Hoses (visual)	~		
D = dent					AD SPT	Transmission		1	
R = rust	s sc				HIV	Operation	~		
PT = paint def	ect N				PT	Noise	~		
C = crack						Clutch			~
P = pin dent	DSC DK				~HHS	CV joints	~		
* = decals		10		70	E PT	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
iii sigiiiicaii	S	C	S	S		Performance	~		
Body Inc	pection Comments	Note: son	ne defects & blemishe	s may not be disp	played in the diagram	Hand Brake	~		
- Front bumper has been taped up on right side, left side has broken clips & is not fitting correctly.						Tyres (lowest observed tread	st observed tread depth of tyres)		
- Front bumper is missing tow hook cover.						Left front	ft front 5.8 m		
	n front grille are broker).				Right front	4	.1	mm
- Stone chips in windscreen. - Paint over sprav on roof and poor paint finish on tailgate & rear bumper.						Left rear		.5	mm
Conditions During Body Inspection: Wet					Right rear		.8	mm	
Conditions During Body Inspection. Wet						Spare		Yes	
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	o on all alloys are missin					Suspension performance	~		
- Plastic trin	n around right side spot	light in front bui				Steering performance	~		
	nd right & left side wing eak around front of eng					Shock absorbers	~		
	ight rear wheel & right					Air Conditioning / Heater	V		
									T
Interior Comments						Operation Electrical / Accessories	~		
	Average								1
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Average					Indicators		~	<u> </u>
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		ļ
						Window winder FL	~		ļ
						Window winder FR		~	
General Comments					Window winder RL		~		
- Glovebox door is broken off. - Stitching split on base of left front seat.					Window winder RR		~		
- CD player	not working as face to s	stereo will not fo	ld down - will need at	tention.		Rear view mirrors	~		
	indicator is not working switch for electric windo		ing off.			Radio (basic test only)	~		
	vs only working from m					CD (basic test only)		~	
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		1
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
								1	
Inspecte	d by: Jason Young					Date: 11 Jan 20	19		
I have read	and understood th	is condition a	uide. Name:			Signature:			