

Report ID: 18,876,571 Version: 1 21 Jan 2019 Created:

Make:	Mazda	Model:	MPV2300	Body Style:	SUV	]		Pass	Fail	N/A	
Year:	2004	Registration:	GAG547	Reg Expiry:	08 Apr 2019	Engine					
WoF Expiry:	09 Jan 2020	Odometer:	110,979 Kms	Good No:	Oil level		~				
VIN:	7AT0C11EX11307515	Next Service:		Service Histor	<b>y:</b> No	Smoke & fur	mes	~			
						Performance	e	~			
	port is not a warranty		for one and miles as	Danta have not	haan diamantlad au	Noise		~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends							Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Coolant condition				
						Performance		レ レ			
Key:	W S		R P SC W P W	R	s	Radiator / H		~			
S = scratch						Transmission		•			
D = dent	s c sc				S PT W	Operation		~			
R = rust PT = paint def				$\prod$	JHH	Noise		· ·			
C = crack				+		Clutch		•		~	
P = pin dent	HIC					CV joints		~			
* = decals	sc 916			- NL	SRP SC	Wheel beari	nas	• •			
SC = stone chips							Brakes				
W = significant scuffs SC S S S S S S S S S S S S S S S S S S						Performance	<b>v</b>				
		Note: som	he defects & blemishes	s may not be disr	laved in the diagram	Hand Brake	-	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							· · · · · · ·			) )	
Headlights need attention,scratch on left tail light,						Tyres (lowest observed tread depth of tyres)   Left front 3					
						Right front		3		mm	
						Left rear		6 mm 3 mm			
										mm	
Conditions During Body Inspection: Dry										mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes					
There is some rust in areas.						Suspension					
There is some rust in areas.						· · · · · · · · · · · · · · · · · · ·	performance	~			
						Steering per		•			
						Shock absor		~			
						Air Condition	ning / Heater				
Interior Comments						Operation 🖌					
rear head rests missing						Electrical / Accessories					
Seats		. coto				Head lights		~			
Carpets	minor stains passengers sided, rip drivers side.				Tail lights		~				
	Average					Indicators		~			
Panels	Average						warning lights	~			
Dashboa	Average			Wipers (fron		~					
						Window wir		~			
Ganaral	-ommonts					Window wir		~			
General Comments Right rear electric sliding door not working.						Window wir		~			
		onang.				Window wir		~			
						Rear view m		~			
						Radio (basic		~			
						CD (basic te		~			
						· · · · · · · · · · · · · · · · · · ·		1	1		
Road Conditions During Test Drive: Dry						Central lock	3	~			
Engine	ming Machanism	Timina	Chain			Remote lock	-	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (ba	sic test only)		~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing ca	amera			~	
Inspected by: Donovan Matara Date: 21 Jan 2019											
	sonovan matar	-				Dat		-			

I have read and understood this condition guide.

Name: .....

Signature: .....