

Report ID: 20,240,859 Version: 1 02 Mar 2020 Created:

P = pin dent * = decals SC = stone chips CV joints CV joints Wheel bearings Problem P = pin dent SC = stone chips SC = stone chips SC = stone chips	
VIN: JM0GG103100127502 Next Service: 0 Service History: No Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. Smoke & fumes ✓ Key: S = scratch S = scratch S = scratch Performance ✓ D = dent S SC S S S S S S S S S S S S S S S S S S S	
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. Key: S S D SC Mote: This report is not a warranty Note: This report is not a warranty S D SC	
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. Key: S S D SC S C S PT SC S = scratch S SC S D SC S D SC S D SC D = dent S SC S D SC S D SC S D SC R = rust S SC S SC S D SC S D SC PT = paint defect C = crack S SC S SC S SC P = pin dent S SC S SC S SC S SC S C = stone chips S SC S SC S SC S SC	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.	
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. Key: S S D SC S SC S PT SC S = scratch D = dent S SC S D SC S D SC S D SC PT = paint defect C crack P = pin dent * S SC S SC S SC Operation ✓ S = scratch D = dent S SC S D SC S D SC S D SC S D SC Transmission Operation ✓ Image: S SC S = stone chips S SC S	
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.	
Key: S S D SC S SC S PT SC S = scratch D = dent S SC S D SC S D SC PT = paint defect C = crack P = pin dent * S SC S SC P = pin dent * S SC S SC S SC S SC S SC S SC S SC S SC S SC P = pin dent * S SC S SC S SC S SC S S = stone chips S SC S SC S SC S SC	
Key: S S D SC S SC S PT SC S = scratch D = dent S SC S D SC S D SC P = paint defect C = crack P = pin dent S SC S SC S SC S = stone chips S SC S S D SC S SC S D SC	
S = scratch D = dent R = rust PT = paint defect C = crack P = pin dent * = decals SC = stone chips SC = stone chips	
D = dent R = rust PT = paint defect C = crack P = pin dent * = decals SC = stone chips D = dent S SC S D SC Operation V Noise V Noise V Clutch CV joints V Previon S SC S Previon S SC	
R = rust PT = paint defect C = crack P = pin dent * = decals SC = stone chips SC Provide the state of the st	
C = crack P = pin dent * = decals SC = stone chips Clutch Clutch CV joints Wheel bearings Prakes	
P = pin dent * = decals SC = stone chips	v
* = decals SC	
SC = stone chips	
Brakes	
W = significant scuffs	
Nate: some defects % blamiches may not be displayed in the disprem	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram Hand Brake	
Tyres (lowest observed tread depth of tyres)	
	ım
	nm
Left rear 7 m	nm
Conditions During Body Inspection: Dry Right rear 3 m	nm
Spare Yes	
Under Carriage & Under Bonnet Inspection Comments Suspension	
Minor oil leak,car needs a service , Suspension performance ✓	
Steering performance 🖌	
Shock absorbers 🖌	
Air Conditioning / Heater	
Operation 🗸	
Interior Comments Electrical / Accessories	
Seats wear and tear, minor stains, Head lights 🖌	
Tail lights	
Carpets Indicators V	
Panels Average Dashboard warning lights ✓	
Wipers (front & rear)	
Dashboard Window winder FL 🖌	
Window winder FR	
General Comments Window winder RL	
Takes a while to start could need a new battery but the vehicle needs a service , Window winder RR	
Rear view mirrors	
L Radio (basic test only)	
Radio (basic test only) ✓ CD (basic test only) ✓	
CD (basic test only)	
CD (basic test only) Number of keys 1	
CD (basic test only) ✓ Number of keys 1 Central locking ✓	
CD (basic test only) ✓ Road Conditions During Test Drive: Dry Engine Timing Mechanism: Timing Chain	
CD (basic test only) ✓ CD (basic test only) ✓ Number of keys 1 Central locking ✓ Remote locking ✓ Remote locking ✓ Sat. Nav. (basic test only) ✓	
Road Conditions During Test Drive: Dry Engine Timing Mechanism: Timing Chain Fundemention Sat. Nav. (basic test only) V V Sat. Nav. (basic test only) V	× ×
CD (basic test only) ✓ CD (basic test only) ✓ Number of keys 1 Central locking ✓ Remote locking ✓ Remote locking ✓ Sat. Nav. (basic test only) ✓	

I have read and understood this condition guide.

Name:

Signature: