

Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments Stone chips in windscreen.

-----

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments Minor oil leak from around engine sump pan.

		Operation	~	
Interior Comments		Electrical / Accessories		
Seats	Good	Head lights	~	
Carpets	Average	Tail lights	~	
		Indicators	~	
Panels	Good	Dashboard warning light	ts 🖌	
Dashboard	Good	Wipers (front & rear)	~	
		Window winder FL	~	
General Comments One of key remotes is not working to lock or unlock vehicle. Boot carpet is dirty & stained. Screw holes in dashboard.		Window winder FR	~	
		Window winder RL	~	
		Window winder RR	~	
		Rear view mirrors	~	
		Radio (basic test only)	~	
		CD (basic test only)	~	
		Number of keys	2	

 Evidence of Cam Belt Replacement:
 Not Applicable
 Kms:
 Reversing camera

 Inspected by:
 Jason Young
 Date: 1

Dry

**Timing Chain** 

Date: 13 Jan 2021

Central locking

Remote locking

Sat. Nav. (basic test only)

Hand Brake

Left front

Left rear

**Right rear** 

Suspension

Suspension performance

Steering performance

Air Conditioning / Heater

Shock absorbers

Spare

**Right front** 

V

3.3

5.0

2.7

3.6

V

V

~

Yes

mm

mm

mm

mm

Tyres (lowest observed tread depth of tyres)

I have read and understood this condition guide.

Road Conditions During Test Drive:

**Engine Timing Mechanism:** 

Name: .....

Signature: .....

V

V

V

V