

| • | Report ID: | 25,989,788 | Version: | 6 | |
|---|------------|-------------|----------|---|--|
| | Created: | 05 Dec 2025 | | | |

| Basic Condition Guide | | Report ID: | 25,989,788 | Ve | rsion: 6 | | | | |
|---|---|-------------------------|--|--|----------------|----------|-----------------------|-----|--|
| | billei | | | Created: | 05 Dec 2025 | | | | |
| Make: | Skoda | Model: | Superb | | | ОК | Requires Attention | | |
| Body Style: | Wagon | Year: | 2021 | Engine | | - OK | Attention | N/A | |
| Rego No.: | NSA60 | Rego Expiry: | 30 Aug 2026 | Oil level | | · / | | | |
| WoF Expiry: | 28 Aug 2026 | Odometer: | 248,607 Kms | Smoke & fu | ımes | · / | | | |
| Good No.: | 25989788 | VIN: | TMBKD9NPXM7054278 | | | 1 | | | |
| Next Service: | 262000 | Service History: | No | Engine performance Noise | | 1 | | | |
| Note: This report is not a warranty | | | | Coolant co | ndition | | | | |
| diagnostic testing un | dertaken. The vehicle has b | een driven up to 50km/l | arts have not been dismantled or h from cold. The Vendor recommends a | Cooling pe | | 1 | | | |
| full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | 1 | | | |
| Key | D | · | | Radiator / Hoses (visual) Transmission | | | | | |
| | = Rust $C = C$ Γ = Paint defect $P = P$ | | ls W = Significant scuffs ne Chips | Operation | | V | | | |
| | | | | Noise | | 1 | | | |
| | W | sc | W | Clutch | | - | | _ | |
| | | | | CV joints | | 1 | | | |
| | | | S SC | Wheel bea | rinas | 1 | | | |
| S SC | | | | Brakes | | | | | |
| sc | | | | Performan | ce | V | | | |
| | | | | Hand brake | | 1 | | | |
| | | | | Tyres (lowest observed tread depth of tyres) | | | | | |
| | | | | Left front | | 4.9 mm | | | |
| sc | | | Right front | | 6.6 mm | | | | |
| | | | Left rear | | 4.3 mm | | | | |
| S | S W S S | | | Right rear | | 5.3 mm | | | |
| Note: some defects | and blemishes may not be | displayed in the diagra | am | Spare | | Yes | | | |
| Body Inspecti | on Comments | | | Suspensio | n | _ | | | |
| Stone chips or | | | | Suspension | n performance | / | | | |
| Holes present | around body from pre | eviously removed li | ghts. | Steering pe | erformance | / | | | |
| | | | | Shock abso | orbers | / | | | |
| Conditions Dur | Conditions During Body Inspection Dry | | | Air Conditioning / Heater | | | | | |
| Under Carriage and Under Bonnet Inspection Comments | | | | Operation | | / | | | |
| Front wheel driv | re | | | Electrical / | Accessories | | | | |
| | | | | Head lights | 5 | / | | | |
| | | | | Tail lights | | / | | | |
| Interior Comments | | | Indicators | | / | | | | |
| Seats: | Good | | | Dashboard | warning lights | / | | | |
| Carpets: | Good | | | Wipers (fro | nt & rear) | / | | | |
| | I | | | | | | | | |

| Interior Comm | ents |
|---------------|----------------------------|
| Seats: | Good |
| Carpets: | Good |
| Panels: | Good |
| Dashboard: | hole in dashboard- Average |

General Comments

- Due for service. Coolant reservoir contains water only.
- Vehicle has a leaking radiator and requires a radiator replacement.
- Missing driver's floor mat.

| | Road Conditions During Test Drive | | Dry | | |
|--|---|---------------|---------|----|-----|
| | Engine Timing Mechanism | | Cambelt | | |
| | Evidence of Cam Belt Replacement Inspected by: Cameron Senior-A | | Yes | No | Kms |
| | | | Arnold | | |
| | Published by: | Kendal Slight | | | |
| | Inspection Date: | 31 Oct 2025 | | | |

| I have read and understood | |
|----------------------------|--|
| this condition guide: | |

| NAME | | | |
|------|--|--|--|

| SIGNATURE | | | |
|-----------|--|--|--|

1

1

1

2

1 1

Window winder FL Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera