

Basic Condition Guide

•	Report ID:	26,049,522	Version:	3
	Created:	24 Nov 2025		

		ОК	Requires Attention	N/A
	Engine			
26	Oil level	/		
NS	Smoke & fumes	V		
3MG014412	Engine performance	V		
	Noise	/		
n dismantled or	Coolant condition	/		
endor recommends a charge.	Cooling performance	V		
	Radiator / Hoses (visual)	V		
= Significant scuffs	Transmission			
3	Operation	V		
SP	Noise	1		
SP	Clutch			1
W	CV joints	1		
VV	Wheel bearings	1		
	Brakes			
111/	Performance	V		
sc	Hand brake	1		
	Tyres (lowest observed tread	depth of	tyres)	·
	Left front	T T		7.5 mn
S	Right front			7.5 mn
	Left rear			5.0 mn
SP	Right rear			5.5 mn
	Spare	Yes		
	Suspension			
	Suspension performance	V		
	Steering performance	1		
	Shock absorbers	1		
_	Air Conditioning / Heater			<u> </u>
	Operation	V		Ι
	Electrical / Accessories		1	
	Head lights	V	<u> </u>	
	Tail lights	1		
	Indicators	1	 	
	Dashboard warning lights	1	-	
	Wipers (front & rear)	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
	Window winder FL	V		
	Window winder FR Window winder FR			
		1		
e of engine bay.	Window winder RL	1		
on engine bay.	Window winder RR	<i>V</i>	-	
	Rear view mirrors	- 1		
	Radio (basic test only)			
	CD (basic test only)			/
	Number of keys	2	1	ı
Kms	Central locking	/		
	Remote locking	/	-	
	Sat. nav. (basic test only)			'
	Reversing camera	/		l

Make:	Subaru	Model:	Outback					
Body Style:	suv	Year:	2022					
Rego No.:	Rego No.: PAK477		26 Jan 2026					
WoF Expiry:	08 Dec 2026	Odometer:	66,187 Kms					
Good No.:	26049522	VIN:	JF2BT9KL3MG014412					
Next Service:	75,000km's	Service History:	Yes					
diagnostic testing un	only. Consideration is made	een driven up to 50km/l	arts have not been dismantled or h from cold. The Vendor recommends a or an additional charge.					
	= Rust C = C = Paint defect P = Pi							
P		SD SP	SP					
Note: some defects a	and blemishes may not be	displayed in the diagra	am					
Body Inspection								
Scratch in window tint on right front drivers door window.								
	Conditions During Body Inspection Wet							
Under Carriage and Under Bonnet Inspection Comments								
Interior Comm	1							
Seats:	Good							
Carpets: Panels:	Average							
	Good							
Dashboard: Good								
General Comments Front windscreen washer is not working, leaks was out bottom left side of engine bay. Carpet worn in right front foot well area.								
Road Condition	s During Test Drive	Dry						
Engine Timing I		Timing Chain						
Evidence of Cam Belt Replacement		Yes	No Kms					

I have read and understood this condition guide:

Inspection Date: 19 Nov 2025

Inspected by:
Published by:

Jason Young

Glen Charlton

NAME ____

SIGNATURE