

•	Report ID:	26,068,764	Version:	1
	Created:	19 Nov 2025		


	ОК	Requires Attention	N/A
Engine	OK	Attention	IN/A
Oil level	V		
Smoke & fumes	/		
Engine performance	V		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	1		
Noise	/		
Clutch			/
CV joints			
Wheel bearings	/		
Brakes			
Performance	1		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			5 mm
Right front			6 mm
Left rear			7 mm
Right rear			7 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater		•	
Operation	1		
Electrical / Accessories			
Head lights	/		
Tail lights	~		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	V		
Window winder FR		~	
Window winder RL	1	1	
	•		
Window winder RR	✓ ✓		
	<i>V</i>		
Window winder RR	V V		
Window winder RR Rear view mirrors	<i>V V</i>		
Window winder RR Rear view mirrors Radio (basic test only)	✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ 2		·
Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)	<i>y</i>		<i>'</i>
Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	2		<i>'</i>
Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	2		

Make:	Suzuki	Model:	Vitara
Body Style:	suv	Year:	2017
Rego No.:	KYP114	Rego Expiry:	18 Jul 2026
WoF Expiry:	21 Nov 2025	Odometer:	205,802 Kms
Good No.:	26068764	VIN:	TSMLYE21S00344584
Next Service:	220,000	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

ney				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Drivers door check strap missing . Drivers inner sill needs painting.inner sill dented.

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Good	

General Comments

Middle. muffler is dented. Steering wheel control is not working properly. CV joints are clicking. Drivers window not working.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by: Lewis Dolamore		
Published by: Lewis Dolamore		
Inspection Date:	19 Nov 2025	

I have read and understood
this condition guide:

NAME			