


Basic Condition Guide

•	Report ID:	27,159,603	Version:	1
	Created:	18 Nov 2025		

	01/	Requires	
Engine	OK	Attention	N/A
Oil level	./		
Smoke & fumes	•		
Engine performance	/		
Noise	<i>'</i>		
Coolant condition			
Cooling performance	•		
Radiator / Hoses (visual)			
Transmission		l I	
Operation	/		
Noise	/		
Clutch			
CV joints	/		
Wheel bearings	/		
Brakes		,	
Performance	~		
Hand brake	'		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		6	6.5 mm
Right front		6	6.5 mm
Left rear		6	6.5 mm
Right rear		2	1.5 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	1		
Electrical / Accessories		•	
Head lights	1		
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL			
Window winder FR	V		
Window winder RL	1		
Window winder RR	·	 	
Rear view mirrors	1		
Radio (basic test only)	1		
	_		
CD (basic test only) Number of keys	2	<u> </u>	
	<i>'</i>	1	
Central locking		-	
Remote locking		-	-1
Sat. nav. (basic test only)			
Reversing camera		<u> </u>	

	JIIIEI			
Make:	Mitsubishi	Model:	Colt	
Body Style:	Hatchback	Year:	2007	
Rego No.:	JZS39	Rego Expiry:	03 Dec 2024	
WoF Expiry:	14 Nov 2026	Odometer:	109,286 Kms	
Good No.:	27159603	VIN:	7AT0CJ0XX16400609	
Next Service:	119,000	Service History:	y: No	
Note: This report is	not a warranty			
diagnostic testing un		een driven up to 50km/l	arts have not been dismantled or h from cold. The Vendor recommends a or an additional charge.	
Key				

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Dents in Right Sill

Large Stone Chips Windscreen

Conditions During Body Inspection	Dry				
Under Carriage and Under Bonnet Inspection Comments					

Underbody Surface Rust

Rear Trailing Arm Bushings Cracked & Perished

Interior Comments		
Seats:	Poor	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
General Comments		

Boot Trims Missing

Road Conditions During Test Drive		Wet
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Samuel Weir	
Published by:	James Scott	
Inspection Date:	18 Nov 2025	

П	nave	read	and	unde	rstood
tł	nis co	nditi	on a	uide	

NAME			

SI	GN	JA.	ΓU	RF